



REPORT OF THROUGH EXAMINATION

This certificate meets the requirements of the (Lifting Operations and Lifting Equipment Regulations 1998)

L.O.L.E.R.

United Powered Access | U.P.A. Court | Lymm Service Area | Cliff Lane | Lymm | WA13 0SP |
Phone: 01925 30 20 20 | www.upa-uk.com

		L.O.L.E.R. SIX MONTHLY EXAMINATION CERTIFICATE NUMBER SD 10/10/25 -01							
		L.O.L.E.R. SIX MONTHLY EXAMINATION CERTIFICATE NUMBER SD 10/10/25 - 01							
MAIN FRAME	Pass	Comments	HYDRAULICS	Pass	Connected	SAFETY WARNING / DECALS	Pass	Comments	
Chasis Condition	/	1	Oil Levels			S.W.L.		1	
Welds	1/	1_	Drive Motor			Number Plate	1	7	
Distortion	1/	1	Check For Residue / Leaks		_	Safety Warning Signs Legible	1	,	
Axle Housing	1/		Replace Hydraulic Filter			Control Operation Decals		7	
Steering Assembly	1/	1	Hydraulic Cylinders / Valves		7	UPA Logo Stickers	1	_	
Cylinder	1/	-	1 Lift Cylinder 1		,	Operator Instruction Manual		7	
Eyes	1		2 Lift Cylinder 2	1	IA	Document Box		/	
King Pins	/		3. Lift Cylinder 3	N	A	Flashing Beacons		7	
Scissor Beams	1		4 Lift Cylinder 4	N	19	Test PPE System	1	_	
Pins	1		5. Platform Extension X 2		-	GENERAL			
Wheel Nut Bolts Torque	1	7	6. Steer Cylinder / Brake		_	Charger Operational			
Tyre Condition	1	-	7. Outriggers X 4	NI	A	Paint Condition	1		
Hub Nuts	1	-	Ram Eyes / Pins	1	_	Free From Debris	1	7	
Brake System Functional		_	Check Hoses Secure	/		Orive Function Test	1	-	
Structural Cracks / Bends	1	/-	Check Hoses Kink / Damage			Drive Cut Out Elevated	A//	1	
Swing Trays / Latches / Inline		-	Hydraulic Pump Secure		_	Low Drive / Elevated	701	3	
Pot Hole Protectors Operational	1	/-	Drive Motors Inspection		_	Full Function Test	1	4	
Rear / Side Steps	1	_	Hydraulic Tank Inspection		_	Outrigger Function Test	ALL	n	
ELECTRICS			Generator Functional	10/1	4	High / Low Throttle	011	6	
Batteries / Levels				100	-	ENGINE/SERVICE	10 11	Ē	
	//		Emergency Descent Test	1	1	TAN AND AND AND AND AND AND AND AND AND A	-		
Leads / Connections / Greasing	11		Emergency Lower Bar Present	\sim 11	7	Engine Oil Change	+	_	
Charger / Sockets	//	1	PLATFORM			Engine Oil Filter Change	-	-	
Power To Platform Socket	//	_	Platform Access Gate Security	//	-	Air Filter Check	-	1	
Volt Meter Functional / Control Box	//	/	Handrails / Locking Pins	//	-	Main Fuel Filter	+	₽	
Manual Horn	//	_	Floor Candition	//	_	Pre Fuel Filter	-/		
Emergency Stop Base	/,	/	Extending Platform / Rollers			Fan Beit Check	-/	_	
Platform	//	_	Harness Anchor Points		_	Alternator Check / Fan	-/-	_	
Isolator	/,	_	Control Box Security			Starter Motor Check	-/-	_	
Descent Alarm	//	/	SCISSOR PACK			Coolant System Check	/	_	
Ground Controls Functional / Key Switch	//	_	Scissor Rollers	//		Oil Leak Check	/	_	
Platform Controls Functional / Key Switch	//	_	Slide Pads	//	_	Engine Tray Stowed		_	
Limit Switches	/	_	Pivat Pins	//		Latches 7 V		_	
Scissor Pack	/	_	Lockers	/	_	Mounting			
Pot Holes	/	,	Bushes		_	Power Track			
Tilt Alarm Sensor Function Test	/	/	Scissor Safety Stay Bar		/	Cables / f			
Platform Overload Sensor	/	,	Scissor Trunnion Box	/		Hases			
Multi Pin Plug Upper Controls	/	1	Scissor Beam Distortion / Welds	/		Engine Post Switches			
Generator Operational / Voltage Check	N	//				Fuel Tank Check / Cap			
PAST EXAMINATION DATES			COMMENTS						
Date Of Last Examination 20 7 7 25				1	- 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Date Of Expiry 21 12	6		Torquad 40 an	J ma	ہار	ed Wheel holds.			
PRESENT DATES	-		- que ap as	4		0000			
Date Of Examination 0/10/25									
Date Of Expiry 01/04-12/			EXAMINED BY:		7				
MACHINE INFORMATION			Print Name	1	1	`^			
Machine Model 506574	11	- +	Sign	1	VII.				
Serial Number SIS32 ox	3-8	6	CAP NO CAP	-	0	21.7			
Date Of Manufacture	10	-	C/ Y	n /	17	25	7		
Sufe Working Load 230. k(-			AUTHENTICATED BY:	0	10	23			
-//-	21.	_		CI	16	MALDA INCILAR			
Fleet Number 06/07 -	74	_	Print Name	21	17	Third vocation		-	
Machine Hours	V.	0	sign	(_	Sibble			