



REPORT OF THROUGH EXAMINATION

This certificate meets the requirements of the
(Lifting Operations and Lifting Equipment Regulations 1998)
L.O.L.E.R.



United Powered Access | U.P.A. Court | Lymm Service Area | Cliff Lane | Lymm | WA13 0SP
Phone: 01925 30 20 20 | www.upa-uk.com

L.O.L.E.R. SIX MONTHLY EXAMINATION CERTIFICATE NUMBER		SD 14/10/25 -01	
MAIN FRAME		Pass	Comments
Chassis Condition	///	///	
Welds	///	///	
Distortion	///	///	
Axle Housing	///	///	
Steering Assembly	///	///	
Cylinder	///	///	
Eyes	///	///	
King Pins	///	///	
Scissor Beams	///	///	
Pins	///	///	
Wheel Nut Bolts Torque	///	///	
Tyre Condition	///	///	
Hub Nuts	///	///	
Brake System Functional	///	///	
Structural Cracks / Bends	///	///	
Swing Trays / Latches / Inline	///	///	
Pot Hole Protectors Operational	///	///	
Rear / Side Steps	///	///	
ELECTRICS		Pass	Comments
Batteries / Levels	///	///	
Leads / Connections / Greasing	///	///	
Charger / Sockets	///	///	
Power To Platform Socket	///	///	
Volt Meter Functional / Control Box	///	///	
Manual Horn	///	///	
Emergency Stop Base	///	///	
Platform	///	///	
Isolator	///	///	
Descent Alarm	///	///	
Ground Controls Functional / Key Switch	///	///	
Platform Controls Functional / Key Switch	///	///	
Limit Switches	///	///	
Scissor Pack	///	///	
Pot Holes	///	///	
Tilt Alarm Sensor Function Test	///	///	
Platform Overload Sensor	///	///	
Multi Pin Plug Upper Controls	///	///	
Generator Operational / Voltage Check	N/A	///	
HYDRAULICS		Pass	Comments
Oil Levels	///	///	
Drive Motor	///	///	
Check For Residue / Leaks	///	///	
Replace Hydraulic Filter	///	///	
Hydraulic Cylinders / Valves	///	///	
1. Lift Cylinder 1	///	///	
2. Lift Cylinder 2	///	N/A	
3. Lift Cylinder 3	///	N/A	
4. Lift Cylinder 4	///	N/A	
5. Platform Extension X 2	X1	///	
6. Steer Cylinder / Brake	///	///	
7. Outriggers X 4	///	N/A	
Ram Eyes / Pins	///	///	
Check Hoses Secure	///	///	
Check Hoses Kink / Damage	///	///	
Hydraulic Pump Secure	///	///	
Drive Motors Inspection	///	///	
Hydraulic Tank Inspection	///	///	
Generator Functional	///	N/A	
Emergency Descent Test	///	N/A	
Emergency Lower Bar Present	///	N/A	
PLATFORM		Pass	Comments
Platform Access Gate Security	///	///	
Handrails / Locking Pins	///	///	
Floor Condition	///	///	
Extending Platform / Rollers	///	///	
Harness Anchor Points	///	///	
Control Box Security	///	///	
SCISSOR PACK		Pass	Comments
Scissor Rollers	///	///	
Slide Pads	///	///	
Pivot Pins	///	///	
Lockers	///	///	
Bushes	///	///	
Scissor Safety Stay Bar	///	///	
Scissor Trunnion Box	///	///	
Scissor Beam Distortion / Welds	///	///	
SAFETY WARNING / DECALS		Pass	Comments
S.W.L.	///	///	
Number Plate	///	///	
Safety Warning Signs Legible	///	///	
Control Operation Decals	///	///	
UPA Logo Stickers	///	///	
Operator Instruction Manual	///	///	
Document Box	///	///	
Flashing Beacons	///	///	
Test PPE System	///	///	
GENERAL		Pass	Comments
Charger Operational	///	///	
Paint Condition	///	///	
Free From Debris	///	///	
Drive Function Test	///	///	
Drive Cut Out Elevated	///	N/A	
Low Drive / Elevated	///	///	
Full Function Test	///	///	
Outrigger Function Test	///	N/A	
High / Low Throttle	///	N/A	
ENGINE / SERVICE		Pass	Comments
Engine Oil Change	///	///	
Engine Oil Filter Change	///	///	
Air Filter Check	///	///	
Main Fuel Filter	///	///	
Pre Fuel Filter	///	///	
Fan Belt Check	///	///	
Alternator Check / Fan	///	///	
Starter Motor Check	///	///	
Coolant System Check	///	///	
Oil Leak Check	///	///	
Engine Tray Stowed	///	///	
Latches	///	///	
Mounting	///	///	
Power Track	///	///	
Cables	///	///	
Hoses	///	///	
Engine Post Switches	///	///	
Fuel Tank Check / Cap	///	///	
PAST EXAMINATION DATES		COMMENTS	
Date Of Last Examination	29/07/25		
Date Of Expiry	28/01/26		
PRESENT DATES		EXAMINED BY:	
Date Of Examination	14/10/25	S. J. M.	
Date Of Expiry	13/04/26	CAP No. 14/02847	
MACHINE INFORMATION		Date	
Machine Model	S0812E11	14/10/25	
Serial Number	P147200231		
Date Of Manufacture	2025		
Safe Working Load	450 kg		
Fleet Number	08/12-29		
Machine Hours			
AUTHENTICATED BY:		SHANNON WELLS	
Print Name		Shannon Wells	
Sign			