



REPORT OF THROUGH EXAMINATION

This certificate meets the requirements of the (Lifting Operations and Lifting Equipment Regulations 1998)

L.O.L.E.R.

United Powered Access | U.P.A. Court | Lymm Service Area | Cliff Lane | Lymm | WA13 0SP Phone: 01925 30 20 20 www.upa-uk.com

MAIN FRAME Chasis Condition		_	R. SIX MONTHLY EXAMINATION CERTIFIC		SD 21110/25 - 02
	.22	l a little and a second			EMO E
Chasis Condition	Pass	Common	HYDRAULICS	Pass	SAFETY WARNING / DECALS
			Oil Levels		S.W.L.
Welds	1		Drive Motor	/,	Number Plate
Distortion	1		Check For Residue / Leaks	//	Safety Warning Signs Legible
Axle Housing	17		Replace Hydraulic Filter		Control Operation Decals
Steering Assembly	1/	t.	Hydraulic Cylinders / Valves	1	UPA Logo Stickers
Cylinder	1/	ĺ.	I, Lift Cylinder 1	1	Operator Instruction Manual
Eyes	1		2 Lift Cylinder 2	NA	Document Box
King Pins	1	1	3. Lift Cylinder 3	NIVA	Flashing Beacons
Scissor Beams	1/		4 Lift Cylinder 4	NIA	Test PPE System
Pins	1	[5. Platform Extension X 2		GENERAL
Wheel Nut Bolts Tarque	1/		6 Steer Cylinder / Brake		Charger Operational
Tyre Condition	1		7. Outriggers X 4	ALIA	Paint Condition
Hub Nuts			Ram Eyes / Pins	14/11	Free From Debris
Brake System Functional			Check Hoses Secure	//	Drive Function Test
Structural Cracks / Bends	1	-	Check Hoses Kink / Damage	//.	Drive Cut Out Elevated
Swing Trays / Latches / Inline	1	-	Hydraulic Pump Secure		Low Drive / Elevated
Pot Hoje Protectors Operational		_	Drive Motors Inspection	1/	Full Function Test
Rear / Side Steps	//	-	Hydraulic Tank Inspection		Outrigger Function Test
ELECTRICS			Generator Functional	NIL	High / Low Thrattle
Batteries / Levels			Emergency Descent Test	1011	ENGINE / SERVICE
	/		Emergency Lower Bar Present	MA	Engine Oil Change
Leads / Connections / Greasing	1		PLATFORM	7711	Engine Oil Filter Change
Charger / Sockets	1				Air Filter Check
Power To Platform Socket	//	-	Platform Access Gate Security		Main Fuel Filter
Volt Meter Functional / Control Box	//	/	Handrails / Locking Pins	-/-	Pre Fuel Filter
Manual Horn	/	-	Floor Condition	//	Fan Belt Check
Emergency Stop Base	/	/	Extending Platform / Rollers	-//-	Alternator Check / Fan
Platform	//		Harness Anchor Points	//	Starter Motor Check
Isolator	1	/	Cantral Box Security		RI
Descent Alarm	//	_	SCISSOR PACK		Coolant System Check
Ground Controls Functional / Key Switch	/,	_	Scissor Rollers	//	Oil Leak Check
Platform Controls Functional / Key Switch	/	_	Slide Pads	//	Engine Tray Stowed
Limit Switches	/	_	Pivot Pins	//	Larches
Scissor Pack	//	-	Lockers		Mounting
Pot Holes	//		Bushes	//	Power Track
Tilt Alarm Sensor Function Test	//	-	Scissor Safety Stay Bar	//	Cables
Platform Overload Sensor		_	Scissor Trunnian Box	//	Hoses
Multi Pin Plug Upper Controls	/	1	Scissor Beam Distortion / Welds		Engine Post Switches
Generator Operational / Voltage Check	N	IA			Fuel Tank Check / Cap
PAST EXAMINATION DATES		^	COMMENTS		
Date Of Last Examination 30/7/	45				
Date Of Expiry 29/11	26				
PRESENT DATES					
Date Of Examination 21/10/25					
			EXAMINED BY:	~^) _r	,
Date Of Expiry 20/04/26			Print Name	A. J.A.	4
LUIUTIA			G :	JV	1
Date Of Expiry 20 04 126 MACHINE INFORMATION Machine Model 55 3217	E		Sign	100	
MACHINE INFORMATION Machine Model S5 2319	E	_	' CAP No	10	2847
MACHINE INFORMATION Machine Model ST 2319	F4.	- 1	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	10	2847
MACHINE INFORMATION Machine Model SJ 3217 Genal Number C 100 1008 Date Of Manufacture 2015	F4 17	k/-	CAP No CA	10	2847
MACHINE INFORMATION Machine Model ST 2319	F4 17,	jk.G	CAP No CA Date 2	SMI	2847 25 ANNON INFLIENS