
REPORT OF THROUGH EXAMINATION





United Powered Access U.P.A. Court Lymm Service Area Cliff Lane Lymm WA13 0SP Phone: 01925 30 20 20 www.upa-uk.com

| | 4.0 | L.E.R. SIX MONTHLY EXAMINATIO | ON CERTIFICATE NUMBE | ALC 31/10/25 | (1) | |
|---|-------|--|----------------------|------------------------------|------|--|
| | | | | Mich of the Jos | | |
| MAIN FRAME | Pass | HYDRAULICS | Pass | SAFETY WARNING / DECALS | Pass | |
| Chasis Condition | 1 | Oil Levels | | S,W.L. | / | |
| Welds | 1 | Drive Motor | | Number Plate | | |
| Distortion | | Check For Residue / Leaks | | Safety Warning Signs Legible | | |
| Axle Housing | 1 | Replace Hydraulic Filter | | Control Operation Decals | / | |
| Steering Assembly | / | Hydraulic Cylinders / Valves | | UPA Logo Stickers | | |
| Cylinder | | 1, Lift Cylinder 1 | | Operator Instruction Manual | | |
| Eyes | / | 2, Lift Cylinder 2 | | Document Box | | |
| King Pins | 1 | 3, Lift Cylinder 3 | SM | Flashing Beacons | / | |
| Scissor Beams | 1 | 4. Lift Cylinder 4 | (10) | Test PPE System | / | |
| Pins | | 5, Platform Extension X 2 | | GENERAL | | |
| | | 6, Steer Cylinder / Brake | | Charger Operational | MS | |
| Wheel Nut Bolts Torque | | | | Paint Condition | | |
| Tyre Condition | | 7, Outriggers X 4 | | Free From Debris | 1 | |
| Hub Nuts | | Ram Eyes / Pins | | | / | |
| Brake System Functional | | Check Hoses Secure | | Drive Function Test | NA | |
| tructural Cracks / Bends | | Check Hoses Kink / Damage | | Drive Cut Out Elevated | 163 | |
| iwing Trays / Latches / Inline | 14 | Hydraulic Pump Secure | | Low Drive / Elevated | / | |
| ot Hole Protectors Operational | M | Drive Motors Inspection | | Full Function Test | 1 | |
| Rear / Side Steps | | Hydraulic Tank Inspection | 10/00 | Outrigger Function Test | / | |
| LECTRICS | | Generator Functional | Ma | High / Low Throttle | _ | |
| atteries / Levels | | Emergency Descent Test | 1 | ENGINE / SERVICE | | |
| eads / Connections / Greasing | | Emergency Lower Bar Present | OA | Engine Oil Change | | |
| harger / Sockets | | PLATFORM | | Engine Oil Filter Change | | |
| ower To Platform Socket | | Platform Access Gate Security | | Air Filter Check | | |
| olt Meter Functional / Control Box | | Handrails / Locking Pins | | Main Fuel Filter | - | |
| Aanual Horn | | Floor Condition | | Pre Fuel Filter | - | |
| mergency Stop Base | | Extending Platform / Rollers | | Fan Belt Check | 1 | |
| Platform | | Harness Anchor Points | | Alternator Check / Fan | | |
| Isolator | | Control Box Security | / | Starter Motor Check | 1 | |
| Descent Alarm | / | SCISSOR PACK | | Coolant System Check | | |
| Ground Controls Functional / Key Switch | | Scissor Rollers | | Oil Leak Check | | |
| Platform Controls Functional / Key Switch | | Slide Pads | | Engine Tray Stowed | | |
| ımıt Switches | / | Pivot Pins | | Latches | | |
| Scissor Pack | / | Lockers | | Mounting | | |
| Pot Holes | MX. | Bushes | | Power Track | | |
| ilt Alarm Sensor Function Test | II) | Scissor Safety Stay Bar | | Cables | | |
| Platform Overload Sensor | / | Scissor Trunnion Box | 1 | Hoses | 1 | |
| Multi Pin Plug Upper Controls | | Scissor Beam Distortion / Welds | | Engine Post Switches | 1 | |
| Senerator Operational / Voltage Check | NE | | | Fuel Tank Check / Cap | | |
| PAST ESPANNATION DATES | 140 | COMMENTS | | | | |
| | 120 | Sandanies. | | | | |
| Date Of Last Examination 4 | 152 | NOU | 115 | | | |
| Date Of Expiry S \ 8 | 1/27 | 1001 | 010 | | | |
| RESENT DATES | 0120 | | | | | |
| ate Of Examination | 0 25 | in a sold | | | | |
| ate Of Expiry 36 (| + 126 | a the symmetry to | 1111 | Kun | | |
| AACHINE HA OHMATION | | Print Name | (VV) (CAS) | | | |
| Nachine Model 081 | 18 | Sign | N. | Minkey | | |
| | 0005 | CAP No | 00 | 00567 | | |
| | 223 | Date | 31 | 0 25 | | |
| afe Working Load | 680K | AVIOLATION ATT | | 110 | 115 | |
| | | | | | | |
| leet Number | 373 | Print Name | | HAMINONO WELLEY | 0_ | |