

**Inspection Carried Out By:**

Hessle Plant Ltd
Canwood Road
Castleford
West Yorkshire
WF10 4PT

Tel: 01977 550557
E-Mail: mail@hessle.co.uk
Web Site: www.hessle.co.uk

Conducted in accordance with CFTS Publication GN28,
Regulation 9 of the 'Lifting Operations and Lifting Equipment Regulations 1998'
and the Provision and Use of Work Equipment Regulations 1998*

Site: NORTH WEST MEWPS UPA LYMM SERVICE AREA CLIFF LANE LYMM, WARRINGTON WA13 0SP	Regular Thorough Examination	
--	-------------------------------------	--

Equip No:	16673	Inspect No:	23635
Make/Model:	MANITOU / M26-4	Job No:	145342
Serial No:	082257	Contact:	ALEX
Last Inspection:	21/10/2025	Inspected:	19/11/2025
Meter:	3768	Printed:	20/11/2025
			Page: 1 of 1

Items to Inspect	Result	Comments
RTE		
Reason For RTE?	Within 12 Month Interval	
Safe Working Load	Yes (Detail)	2600kg
Date Of Manufacture	Yes (Detail)	2017
Is this the first examination after installation or assembly at new site/location?	No	
If Yes to above, has the equipment been installed correctly?	Not Applicable	
A Defects	None	
Timescale For A Defect Repairs	Not Applicable	
B Defects	Yes (Detail)	Beacons inop
Timescale For B Defect Repairs	1 Month	
C Observations	None	
Particulars of any tests carried out as part of examination	No	
I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28	The Equipment can be used within timescale	
Is Machine Safe to use?	Yes	
Date Of Next Inspection	Yes (Detail)	19-11-2026

DECLARATION BY COMPETENT PERSON

I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28