



REPORT OF THROUGH EXAMINATION

This certificate meets the requirements of the
(Lifting Operations and Lifting Equipment Regulations 1998)
L.O.L.E.R.



United Powered Access | U.P.A. Court | Lymm Service Area | Cliff Lane | Lymm | WA13 0SP
 Phone: 01925 30 20 20 | www.upa-uk.com

L.O.L.E.R. SIX MONTHLY EXAMINATION CERTIFICATE NUMBER

SD 19/01/26 - 01

| MAIN FRAME | Pass | Comments | HYDRAULICS | Pass | Comments | SAFETY WARNING / DECALS | Pass | Comments |
|---|------|----------|-------------------------------|------|----------|------------------------------|------|----------|
| Chassis Condition | / | | Oil Levels | / | | SWL | / | |
| Welds | / | | Drive Motor | / | | Number Plate | / | |
| Distortion | / | | Check For Residue / Leaks | / | | Safety Warning Signs Legible | / | |
| Axle Housing | / | | Replace Hydraulic Filter | / | | Control Operation Decals | / | |
| Steering Assembly | / | | Hydraulic Cylinders / Valves | / | | UPA Logo Stickers | / | |
| Cylinder | / | | 1. Lift Cylinder 1 | / | | Operator Instruction Manual | / | |
| Eyes | / | | 2. Lift Cylinder 2 | / | | Document Box | / | |
| Pin Pins | / | | 3. Lift Cylinder 3 | / | N/A | Flashing Beacons | / | |
| Scissor Beams | / | | 4. Lift Cylinder 4 | / | N/A | Test PPE System | / | |
| Pins | / | | 5. Platform Extension X 2 | / | X1 | GENERAL | | |
| Wheel Nut Bolts Torque | / | | 6. Steer Cylinder / Brake | / | | Charger Operational | / | |
| Tyre Condition | / | | 7. Outriggers X 4 | / | N/A | Paint Condition | / | |
| Hub Nuts | / | | Rim Eyes / Pins | / | | Free From Debris | / | |
| Brake System Functional | / | | Check Hoses Secure | / | | Drive Function Test | / | |
| Structural Cracks / Bends | / | | Check Hoses / Ink / Damage | / | | Drive Cut Out Elevated | / | N/A |
| Swing Trays / Latches / In Line | / | | Hydraulic Pump Secure | / | | Low Drive / Elevated | / | |
| Post Hole Protectors Operational | / | | Drive Motors Inspection | / | | Full Function Test | / | |
| Rear / Side Steps | / | | Hydraulic Fork Inspection | / | | Outrigger Function Test | / | N/A |
| ELECTRICS | | | Generator Functional | / | N/A | High / Low Throttle | / | N/A |
| Batteries / Levels | / | | Emergency Descent Test | / | | ENGINE / SERVICE | | |
| Loads / Connections / Greasing | / | | Emergency Lower Bar Present | / | N/A | Engine Oil Change | / | |
| Charger / Sockets | / | | PLATFORM | | | Engine Oil Filter Change | / | |
| Power To Platform Socket | / | | Platform Access Gate Security | / | | Air Filter Check | / | |
| Volt Meter Functional / Control Box | / | | Handrails / Locking Pins | / | | Via In Fuel Filter | / | |
| Manual Horn | / | | Floor Condition | / | | Pre Fuel Filter | / | |
| Emergency Stop Brake | / | | Extending Platform / Rollers | / | | Fan Belt Check | / | |
| Platform | / | | Harness Anchor Points | / | | Alternator Check / Fan | / | |
| Isolator | / | | Control Box Security | / | | Starter Motor Check | / | |
| Descent Alarm | / | | SCISSOR PACK | | | Coolant System Check | / | |
| Ground Controls Functional / Key Switch | / | | Scissor Rollers | / | | Oil Leak Check | / | |
| Platform Controls Functional / Key Switch | / | | Slide Pads | / | | Engine Tray / Stowage | / | N |
| Limit Switches | / | | Pivot Pins | / | | Latches | / | |
| Scissor Pack | / | | Lubricant | / | | Mounting | / | |
| Post Holes | / | | Bushes | / | | Power Track | / | |
| Pin Alarm Sensor Functional Test | / | | Scissor Safety Stop Bar | / | | Cables | / | |
| Platform Overload Sensor | / | | Scissor Tunnion Box | / | | Mount | / | |
| Multi Pin Plug / Loper Controls | / | | Scissor Beam Distortion / Oil | / | | Engine Post Switches | / | |
| Generator Operational / Voltage Check | / | N/A | | | | Fuel Tank Check / Cap | / | |

PAST EXAMINATION DATES

Date Of Last Examination: 11/08/25
 Date Of Expiry: 10/02/26

PRESENT DATES

Date Of Examination: 19/01/26
 Date Of Expiry: 18/07/26

MACHINE INFORMATION

Machine Model: AS1413E
 Serial Number: M13300087
 Date Of Manufacture: 2021
 Safe Working Load: 320 kg
 Fleet Number: 14/13-01
 Machine Hours: 104

COMMENTS

Torqued up all wheel studs.

EXAMINED BY:

Print Name: S. L. CAPTAIN
 Sign: [Signature]
 Date: 19/01/26

AUTHENTICATED BY:

Print Name: SHANNON WELTENS
 Sign: [Signature]

