



Inspection Carried Out By:

**Hessle Plant Ltd**

Carrwood Road  
Castleford  
West Yorkshire  
WF10 4PT

Tel: 01977 550557  
E-Mail: mail@hessle.co.uk  
Web Site: www.hessle.co.uk

Conducted in accordance with CFTS Publication GN28,  
Regulation 9 of the 'Lifting Operations and Lifting Equipment Regulations 1998'  
and the 'Provision and Use of Work Equipment Regulations 1998'

**Site:** NORTH WEST MEWPS SERVICES LTD  
CA ROOFING SERVICES  
C/O MCLAREN CONSTRUCTION  
PLOT 1, POANATTONI PARK  
A419 / A361  
SN3 4TZ

## Regular Thorough Examination

**Equip No:** 17643

**Make/Model:** MANITOU / M30-4 -13

**Serial No:** L01155313

**Last Inspection:** 09/04/2025

**Meter:** 568

**Inspect No:** 26567

**Job No:** 149179

**Contact:** MICHAEL

**Inspected:** 31/03/2026

**Printed:** 31/03/2026

Page: 1 of 1

Items to Inspect	Result	Comments
<b>RTE</b>		
Reason For RTE?	Within 12 Month Interval	
Safe Working Load	Yes (Detail)	3000kg
Date Of Manufacture	Yes (Detail)	2025
Is this the first examination after installation or assembly at new site/ location?	No	
If Yes to above, has the equipment been installed correctly?	Not Applicable	
A Defects	None	
Timescale For A Defect Repairs	Not Applicable	
B Defects	None	
Timescale For B Defect Repairs	Not Applicable	
C Observations	Yes (Detail)	Service due, service light on dash. Up/down lever loose, tightened nut now ok. Chains 0.25% elongation. Hydraulic oil on minimum.
Particulars of any tests carried out as part of examination	No	
I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28	No Faults Have Been Detected	
Is Machine Safe to use?	Yes	
Date Of Next Inspection	Yes (Detail)	31/3/27

**DECLARATION BY COMPETENT PERSON**

I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28

Engineer Name: Matt Knight

Customer Name: Ross

Signature:

Signature:

Name of the person authenticating this report on behalf of the author :-

Name: Cameron Scott

Signature:

Name and address of Company responsible for this Thorough Examination  
Hessle Fork Trucks - Head Office, Carrwood Road, Castleford, WF10 4PT