REPORT OF THROUGH EXAMINATION

This certificate meets the requirements of the
(Lifting Operations and Lifting Equipment Regulations 1998)

L.O.L.E.R.

United Powered Access U.P.A. Court Lymm Service Area Cliff Lane Lymm WA13 0SP
Phone: 01925 30 20 20 www.upa-uk.com

L.O.L.E.R. SIX MONTHLY EXAMINATION CERTIFICATE NUMBER SD 12/10/26-01

MAIN FRAME	Pass	[illegible]
Chassis Condition	✓	
Welds	✓	
Distortion	✓	
Axle Housing	✓	
Steering Assembly	✓	
Cylinder	✓	
Eyes	✓	
King Pins	✓	
Scissor Beams	✓	
Pins	✓	
Wheel Nut Bolt Torque	✓	
Tyre Condition	✓	
Hub Nuts	✓	
Brake System Functional	✓	
Structural Cracks / Bends	✓	
Lifting Points / Lashing [illegible]	✓	
Pot Hole Protection Operational	✓	
Rear / Side steps	✓	

ELECTRICS	Pass
Batteries / Levels	✓
Leads / Connections / [illegible]	✓
Charger / [illegible]	✓
Power To Platform [illegible]	✓
[illegible] Function [illegible] / Control Box	✓
[illegible]	✓
Emergency Stop [illegible]	✓
[illegible]	✓
[illegible]	✓
[illegible] Alarm	✓
Ground Control [illegible] Switch	✓
Platform Control [illegible] Switch	✓
Limit Switches	✓
[illegible]	✓
[illegible]	✓
Tilt Alarm [illegible] Function Test	✓
[illegible]	✓
[illegible]	✓
Generator Operation / Voltage Check	N/A

HYDRAULICS	Pass
Oil Levels	✓
Drive [illegible]	✓
Check For Residue / Leaks	✓
Replace Hydraulic Filter	N/A
Hydraulic Cylinders / Valves	✓
1 Lift Cylinder	✓
2 Lift Cylinder 2	N/A
3 Lift Cylinder 3	N/A
4 Lift Cylinder 4	N/A
5 Platform Extension [illegible]	✓
6 Steer Cylinder / Brake	✓
7 Outrigger [illegible]	N/A
Ram [illegible] / Pins	✓
Check Hoses Secure	✓
Check Hoses Wear / Damage	✓
Hydraulic Pump Secure	✓
Drive Motor [illegible]	✓
Hydraulic Tank Inspection	✓
Generator Functional	N/A
Emergency Descent Test	✓
Emergency Lower Bar Present	N/A

X1

PLATFORM	Pass
Platform Access Gate Security	✓
Handrails / Locking Pins	✓
Floor Condition	✓
Extending Platform / Rollers	✓
Harness Anchor Points	✓
Control Box Security	✓

SCISSOR PACK	Pass
[illegible]	✓
Slide Pads	✓
Pivot Pins	✓
[illegible]	✓
Bushes	✓
[illegible]	✓
[illegible]	✓
[illegible]	✓

SAFETY WARNING / DECALS	Pass
S.W.L.	✓
Number Plate	✓
Safety Warning Signs Legible	✓
Control Operation Decals	✓
UPA Logo Stickers	✓
Operator Instruction Manual	✓
Document Box	✓
Flashing Beacons	✓
Test PPE System	✓

GENERAL	Pass
Charger Operational	✓
Paint Condition	✓
Free From Debris	✓
Drive Function Test	✓
Drive Cut Out Elevated	N/A
Slow Drive / Elevated	✓
Full Function Test	✓
Outrigger Function Test	N/A
High / Low Throttle	N/A

ENGINE / SERVICE	
Engine Oil Change	N/A
Engine Oil Filter Change	
Air Filter Check	
Main Fuel Filter	
Pre Fuel Filter	
Fan Belt Check	
Alternator Check / Fan	
Starter Motor Check	
Coolant System Check	
Oil Leak Check	
Engine Tray Stowed	
[illegible]	
Mounting	
Power Track	
Cables	
Hoses	
Engine Parts [illegible]	
Fuel Tank Check / Cap	

17/06/26
18/12/26

12/10/26
11/04/27

S0607E II
P338200470
2023
230 kgs.
06/07-27
75

Poor paintwork in areas

S Duffy
CAP /02847
12 10 26

SHANNON WELLENS