



Inspection Carried Out By:

Hessle Plant Ltd

Carrwood Road
Castleford
West Yorkshire
WF10 4PT

Tel: 01977 550557
E-Mail: mail@hessle.co.uk
Web Site: www.hessle.co.uk

Conducted in accordance with CFTS Publication GN28,
Regulation 9 of the 'Lifting Operations and Lifting Equipment Regulations 1998'
and the 'Provision and Use of Work Equipment Regulations 1998'

Site: NORTH WEST MEWPS LTD
C/O MCLAREN CONSTRUCTION
KINGSTANDING PARK
TUNBRIDGE WELLS
KENT
TN2 3UP

Regular Thorough Examination

Equip No: 16293

Make/Model: MANITOU / M26-4

Serial No: 981837

Last Inspection:

Meter: 3716

Inspect No: 35602

Job No: 163116

Contact: CARL

Inspected: 22/09/2026

Printed: 12/10/2026

Page: 1 of 1

Items to Inspect	Result	Comments
RTE		
Reason For RTE?	Within 12 Month Interval	
Safe Working Load	Yes (Detail)	2600kg
Date Of Manufacture	Yes (Detail)	2017
Is this the first examination after installation or assembly at new site/ location?	No	
If Yes to above, has the equipment been installed correctly?	Not Applicable	
A Defects	None	
Timescale For A Defect Repairs	Not Applicable	
B Defects	None	
Timescale For B Defect Repairs	Not Applicable	
C Observations	Yes (Detail)	Chains are 1% wear but would recommend new ones as covered in thick dirt
Particulars of any tests carried out as part of examination	No	
I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28	No Faults Have Been Detected	
Is Machine Safe to use?	Yes	
Date Of Next Inspection	Yes (Detail)	22/09/2027

DECLARATION BY COMPETENT PERSON

I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28

Engineer Name: Chris Whiting

Customer Name: Customer Not Present

Signature:

Signature:

Name of the person authenticating this report on behalf of the author :-

Name: Cameron Scott

Signature: [Signature]

Name and address of Company responsible for this Thorough Examination

Hessle Fork Trucks - Head Office, Carrwood Road, Castleford, WF10 4PT

FT/264-01