# REPORT OF THROUGH EXAMINATION

This certificate meets the requirements of the
**(Lifting Operations and Lifting Equipment Regulations 1998)**

## L.O.L.E.R.

**United Powered Access** | U.P.A. Court | Lymm Service Area | Cliff Lane | Lymm | WA13 0SP
Phone: 01925 30 20 20 | www.upa-uk.com

L.O.L.E.R. SIX MONTHLY EXAMINATION CERTIFICATE NUMBER: 03/3/11/2026-01

| MAIN FRAME | Pass | Comments |
|---|---|---|
| Chasis Condition | ✓ | |
| Welds | ✓ | |
| Distortion | ✓ | |
| Axle Housing | ✓ | |
| Steering Assembly | ✓ | |
| Cylinder | ✓ | |
| Eyes | ✓ | |
| King Pins | ✓ | |
| Scissor Beams | ✓ | |
| Pins | ✓ | |
| Wheel Nut Bolts Torque | ✓ | |
| Tyre Condition | ✓ | ✓ |
| Hub Nuts | ✓ | |
| Brake System Functional | ✓ | |
| Structural Cracks / Bends | ✓ | |
| Swing Trays / Latches / Inline | ✓ | |
| Pot Hole Protectors Operational | ✓ | |
| Rear / Side Steps | ✓ | |
| **ELECTRICS** | | |
| Batteries / Levels | ✓ | |
| Leads / Connections / Greasing | ✓ | |
| Charger / Sockets | ✓ | |
| Power To Platform Socket | ✓ | |
| Volt Meter Functional / Control Box | ✓ | |
| Manual Horn | ✓ | |
| Emergency Stop Base | ✓ | |
| Platform | ✓ | |
| Isolator | ✓ | |
| Descent Alarm | ✓ | |
| Ground Controls Functional / Key Switch | ✓ | |
| Platform Controls Functional / Key Switch | ✓ | |
| Limit Switches | ✓ | |
| Scissor Pack | ✓ | |
| Pot Holes | ✓ | |
| Tilt Alarm Sensor Function Test | ✓ | |
| Platform Overload Sensor | ✓ | |
| Multi Pin Plug Upper Controls | ✓ | |
| Generator Operational / Voltage Check | N/A | |

| HYDRAULICS | Pass | Comments |
|---|---|---|
| Oil Levels | ✓ | |
| Drive Motor | ✓ | |
| Check For Residue / Leaks | ✓ | |
| Replace Hydraulic Filter | N/A | |
| Hydraulic Cylinders / Valves | ✓ | |
| 1. Lift Cylinder 1 | ✓ | |
| 2. Lift Cylinder 2 | N/A | |
| 3. Lift Cylinder 3 | N/A | |
| 4. Lift Cylinder 4 | N/A | |
| 5. Platform Extension X 2 | ✓ | |
| 6. Steer Cylinder / Brake | ✓ | |
| 7. Outriggers X 4 | N/A | |
| Ram Eyes / Pins | ✓ | |
| Check Hoses Secure | ✓ | |
| Check Hoses Kink / Damage | ✓ | |
| Hydraulic Pump Secure | ✓ | |
| Drive Motors Inspection | ✓ | |
| Hydraulic Tank Inspection | ✓ | |
| Generator Functional | N/A | |
| Emergency Descent Test | ✓ | |
| Emergency Lower Bar Present | N/A | |
| **PLATFORM** | | |
| Platform Access Gate Security | ✓ | |
| Handrails / Locking Pins | ✓ | |
| Floor Condition | ✓ | |
| Extending Platform / Rollers | ✓ | |
| Harness Anchor Points | ✓ | |
| Control Box Security | ✓ | |
| **SCISSOR PACK** | | |
| Scissor Rollers | ✓ | |
| Slide Pads | ✓ | |
| Pivot Pins | ✓ | |
| Lockers | ✓ | |
| Bushes | ✓ | |
| Scissor Safety Stay Bar | ✓ | |
| Scissor Trunnion Box | ✓ | |
| Scissor Beam Distortion / Welds | ✓ | |

| SAFETY WARNING / DECALS | Pass | Comments |
|---|---|---|
| S.W.L. | ✓ | |
| Number Plate | ✓ | |
| Safety Warning Signs Legible | ✓ | |
| Control Operation Decals | ✓ | |
| UPA Logo Stickers | ✓ | |
| Operator Instruction Manual | ✓ | |
| Document Box | ✓ | |
| Flashing Beacons | ✓ | |
| Test PPE System | ✓ | |
| **GENERAL** | | |
| Charger Operational | ✓ | |
| Paint Condition | ✓ | |
| Free From Debris | ✓ | |
| Drive Function Test | ✓ | |
| Drive Cut Out Elevated | N/A | |
| Low Drive / Elevated | ✓ | |
| Full Function Test | ✓ | |
| Outrigger Function Test | N/A | |
| High / Low Throttle | N/A | |
| **ENGINE / SERVICE** | | |
| Engine Oil Change | | |
| Engine Oil Filter Change | | |
| Air Filter Check | | |
| Main Fuel Filter | | |
| Pre Fuel Filter | | |
| Fan Belt Check | | |
| Alternator Check / Fan | | |
| Starter Motor Check | | |
| Coolant System Check | | |
| Oil Leak Check | | |
| Engine Tray Stowed | | |
| Latches | | |
| Mounting | | |
| Power Track | | |
| Cables | | |
| Hoses | | |
| Engine Post Switches | | |
| Fuel Tank Check / Cap | | |

| PAST EXAMINATION DATES | |
|---|---|
| Date Of Last Examination | 1/7/2026 |
| Date Of Expiry | 30/12/2026 |
| **PRESENT DATES** | |
| Date Of Examination | 3/11/2026 |
| Date Of Expiry | 2/5/2027 |
| **MACHINE INFORMATION** | |
| Machine Model | LGMA - 06/07 |
| Serial Number | 1320 0105 |
| Date Of Manufacture | 2021 |
| Safe Working Load | 290kg |
| Fleet Number | 06/07/02 |
| Machine Hours | 106 |

**COMMENTS**
WEAR ON TYRES - MONITOR

| EXAMINED BY: | |
|---|---|
| Print Name | DARREN GIBSON |
| Sign | |
| CAP No | 04370 |
| Date | 3 / 11 / 2026 |
| **AUTHENTICATED BY:** | |
| Print Name | SHANNON WELLENS |
| Sign | |

White Copy: Machine File | Pink Copy: HQ
This L.O.L.E.R. report has been endorsed by the manufacturer of this machine, SKYJACK