



Customer
Contact

Resource

Vlad Bitere

Address

Job type

EP-Stage 1B VR Test

Reference

ST1-5949

Date

09/10/2025 15:43 - 16:26

Billing address

Job duration

00:43:00

Driving duration

00:00:03

Distance travelled

0 mi

Notes

VR1 Inspection



A. Opening Clearance Certificate

	Answer	Notes
Key control measures: Site manager to select to confirm use)	Gas Monitor,Barrier,Fire Extinguisher	
PPE requirement: (Site manager select to confirm use)	Hard hat,Safety Glasses,Gloves,Boots,High Vis,Task specific PPE	
Are there any additional hazards identified in the last minute risk assessment	No	
Has the site seen the risk assessment/method statement/ JHA	Yes	
Have you made the site aware the number of operatives in your team or if you are a lone worker?	Yes	
Has the site register been signed?	Yes	
Team leader confirmation	STATEMENT READ - I confirm that I have read, understood and will abide by the Eurotank safety method statement and risk assessment related to tasks	
Team leader	Vlad Bitere	


Site operator confirmation	STATEMENT READ - I confirm that I have read and understood the Eurotank safety method statement and risk assessment related to tasks and authorise the work to proceed
-----------------------------------	--

Site operator	AYISHA
----------------------	--------

B.1. Site Setup

Answer	Comments
Take a Picture of your safe working area on the forecourt include fire ex, gas monitor and barriers	
1. additional photo of setup area	No
Site setup complete correctly	Yes

C. Stage 1b inspection and test

Answer	Notes
Take a picture of the gauge print out	
Does the print out match the tank to pump plan and labels?	Yes

Take a picture of the
forecourt



Take a picture of a pump



Take a photo of the Vent
stack



Where is the manifold

Low

located?

Where are the fill points? Above Ground, Off Set

How many Pvs? 2

How many Dcs 6 7 DCS

Is the vent warning sign in place? Yes

Are vent tags in place? Yes

Take a photo of the Fill Points



Are the labels clean? Yes

Are there OPDs on site? No

Are only two hose connect v first signs in place? Yes

Check cap seals STATEMENT READ - Check all spirit and diesel cap o,ring seals and replace as required

Take a photo of your test rig on the fill points testing drop tube seals



Is the vent system sound
and undamaged?

Yes

Have you emptied the drain
valve?

No drain valve

Take a photo of the Pvs on
test from the cherry picker
bucket.



Are the pvs operating
correctly?

Yes

Is the vr hook adapter free
and operational?

Yes

Take a photo of the VR
adaptor and flame arrestor



Please take a picture of your setup around chambers



Details the size(s) and type of the manhole cover (Eg. Fibrelite 860 x 860)

980mm x 980mm fibrelite

Tank on site details, please state which number, a photo of the current tank , the labels, how deep is the chamber etc

STATEMENT READ - Tank on site details, please state which number, a photo of the current tank , the labels, how deep is the chamber etc

What is the tank number?

8

Take a photo of the current manhole chamber



How deep is the manhole chamber

1200mm

Are the tank labels visible with no damage

Yes

Does the chamber contain water over fixtures and fittings?

Yes

Are you working on another tank Yes

What is the tank number? 7

Take a photo of the current manhole chamber



How deep is the manhole chamber 1200mm

Are the tank labels visible with no damage Yes

Does the chamber contain water over fixtures and fittings? No

Are you working on another tank Yes

What is the tank number? 6

Take a photo of the current manhole chamber



How deep is the manhole chamber 1200mm

Are the tank labels visible
with no damage

Yes

Does the chamber contain
water over fixtures and
fittings?

No

Are you working on another
tank

Yes

What is the tank number?

5

Take a photo of the current
manhole chamber



How deep is the manhole
chamber

1200mm

Are the tank labels visible
with no damage

Yes

Does the chamber contain
water over fixtures and
fittings?

No

Are you working on another
tank

Yes

What is the tank number?

4

Take a photo of the current manhole chamber



How deep is the manhole chamber

1400mm

Are the tank labels visible with no damage

Yes

Does the chamber contain water over fixtures and fittings?

No

Are you working on another tank

Yes

What is the tank number?

3

Take a photo of the current manhole chamber



How deep is the manhole chamber

1400mm

Are the tank labels visible with no damage

Capacity labels in bad condition

Does the chamber contain

Yes

water over fixtures and fittings?

Are you working on another tank Yes

What is the tank number??? 2

Take a photo of the current manhole chamber



How deep is the manhole chamber 1400mm

Are the tank labels visible with no damage Capacity labels in bad condition

Does the chamber contain water over fixtures and fittings? Yes

Are you working on another tank Yes

What is the tank number?? 1

Take a photo of the current manhole chamber



How deep is the manhole chamber	1450mm
Are the tank labels visible with no damage	Capacity labels in bad condition
Are, This Tank Is Manifolde, Grade and Capacity labels fitted ?	No
which of the "This Tank Is Manifolde", Grade and Capacity labels are missing?	Capacity labels for tank 1, tank2 ,tank3 in bad condition
Are the ducts sealed?	Yes
Which leak detection system is fitted?	Probe
Are there any other issues, this includes bad condition of any visible?	Yes
List any issues found or observations	Capacity labels for tank 1, tank2 ,tank 3 in bad condition
Confirm if this test is a Pass or Fail	Pass

Z. Closing out a Clearance Certificate (Europump)

	Answer	Notes
Give a summary of the work completed (NOTE - These details will automatically be sent to the customer)	Vr tested pass Off set check holding pressure test Chambers check	Capacity labels for tank 1, tank2 ,tank 3 in bad condition
Have you used any parts	No	
Have you advised the site staff details of all the work completed	Yes	
Have you signed out of the site register and customer specific software	Yes	
Has the site operator been made aware of any isolations	Yes	
Are the site aware of any alterations made?	Yes	

Have all site keys and property been returned to the Kiosk	Yes
CC fully completed and signed by contractor & site operator?	Yes
Team leader confirmation	STATEMENT READ - I confirm that the work has been completed to my satisfaction and left in a safe condition
Team leader	Vlad Bitere

Site operator confirmation	STATEMENT READ - I confirm that the work has been completed to my satisfaction and left in a safe condition
Site operator	AYISHA

Is there any additional work or issues on site ?	No
--	----

eurotank

Keeping your fuel flowing

**Eurotank
Environmental
Ltd**

47 Bolton Brow
Sowerby Bridge,
Halifax
HX6 2AL

eurotank

Keeping your fuel flowing

**Eurotank
Environmental
Ltd**

47 Bolton Brow
Sowerby Bridge,
Halifax
HX6 2AL