



# PERSPECTIVE

ARCHITECTS, PLANNERS, ENGINEERS & INTERIOR DESIGNER

## HEAD OFFICE

Flat no-3D, 3rd Floor  
PURUSOTTAM ENCLAVE, Abhai Path,  
(Opp. Indian oil Petrol pump), Wireless,  
Guwahati-06, Assam  
Mobile No: +91-9864159678  
E-mail:- [perspective.dm@gmail.com](mailto:perspective.dm@gmail.com)

## BRANCH OFFICE

CHAPPA GURI ROAD  
NORTH BONGAIGAON,  
ASSAM. 783380  
Mobile No: +91-9435020794  
E-mail:- [basumatarymriduraj@gmail.com](mailto:basumatarymriduraj@gmail.com)

Certificate No: BFC/011/21082025

## **BUILDING FITNESS CERTIFICATE**

1. Name of the School: **AXEL PUBLIC SCHOOL**
2. Location: Thapana Road, Lokhara, Guwahati-29, Kamrup(M), Assam
3. Classification of Building: RCC (G+2) Frame Structure having 3 nos of Block. Year of Construction in 2011.
  - i) No of Class Room =  $20' \times 24' \times 11' = 41$  Nos + 8ft Veranda
  - ii) Science Lab =  $20' \times 36' \times 11' = 3$  nos,      iii) Computer lab =  $20' \times 24' \times 11' = 2$  nos
  - iv) Library = 1700 Sq.ft,      v) Administration = 3400 Sq.ft
  - vi) Staff Room = 800 Sq.ft      vii) Medical Room = 800 Sq.ft
  - viii) Boys & Girls Toilet Block Each Floor, ix) Staircase = 3nos
  - x) Swimming Pool, Basketball court, Badminton court & Children play area.
4. Period for which the certificate is issued = 3 (Three) Years
5. Nature of defects, if any,
  - a) RCC Frame Sub-Structure & Superstructure = No
  - b) Doors, Windows, Railing & wood works = No
  - c) Floors = No
  - d) Roof = No
  - e) Miscellaneous (Cracks, etc) = No

This is certified that the school building was inspected by me on 20.08.2025 and found to be fit to conduct classes for the period of three years for the reasons stated above.

**M/s PERSPECTIVE**

(Debojit Sonowal)

Regd. No: GMDA/RTP/2015/Gr(Engg/Arch)-07/25  
TP/RTP/08/Agency/Gr. Jan/23/12  
Wireless, Guwahati-06, Assam,



Dated: 21.08.2025