

Scan ID: 190388

Date: 2025-04-29

GPS Coordinates:

**Accessibility Grade** 

**Access Description** 

4 out of 5

Minor Barriers to Access Found

Material

Concrete

Length Inspected

152 ft

**Area Inspected** 

764 ft<sup>2</sup>

Detectable No DW Warning Necessary **Percent** 0% **Deteriorated** 

# **GPS IMAGES AND COORDINATES HAVE BEEN** REMOVED FROM THIS FILE FOR DATA PRIVACY



## **Scan Data**

Metadata				
Scan ID	190388			
Inspection Date	2025-04-29			
GPS Coordinates				
Accessibility Grade	4			
Access Description	Minor Barriers to Access Found			
Material	Concrete			
Detectable Warning	No DW Necessary			
Length Inspected	152 ft			
Area Inspected	764 ft²			

Condition Areas			
Cracked Area	0 ft <sup>2</sup> 0		
Deteriorated Area	ft <sup>2</sup> 764		
Panel Area	ft <sup>2</sup> 0%		
Percent Deteriorated			

Slopes & Measurements			
Average Cross Slope	2.3%		
Max Cross Slope	3.7%		
Average Running Slope	0.9%		
Max Running Slope	2.0%		
Average Width	57.7 in		
Min Clear Width	53.0 in		

Violations						
Cross Slope	Э	Running Si	Running Slope		Clear Width	
Extreme	0	Extreme	0	Extreme	0	
Severe	0	Severe	0	Severe	0	
Moderate	12	Moderate	0	Moderate	0	
Minor	2	Minor	0	Minor	0	



a. o occiamatos.

## **Annotated Raster Legend**

#### **Ramp Violation Thresholds**

	Cross Slope		Run Slo	Run Slope		Width	
Severity							
Minor	2.5% - 3%	CS	8.3% - 9%	RS	42" - 46"		
Moderate	3% - 4%	cs	9% - 10%	RS	36" - 42"	CW	
Severe	4% - 6%	cs	10% - 12%	RS	24" - 36"	CW	
Extreme	6+%	cs	12+%	RS	0" - 24"	(cw)	
Score Impact	High		High		High		

### **Regions**



#### **Midblock Violation Thresholds**

	Cross Slope		Run Slope		Width	Width	
Severity							
Minor	2.5% - 3%	cs	8.3% - 9%	RS	42" - 46"		
Moderate	3% - 4%	cs	9% - 10%	RS	36" - 42"	CW	
Severe	4% - 6%	cs	10% - 12%	RS	24" - 36"	CW	
Extreme	6+%	cs	12+%	RS	0" - 24"	(cw)	
Score Impact	High		High		High		

#### **Manual Tags**





