



Scan ID: 199378

Date: 2025-06-09

GPS Coordinates:

Accessibility Grade

**Access Description** 

4 out of 5

Minor Barriers to Access Found Material

Concrete

Length Inspected

226 ft

Area Inspected 1092 ft<sup>2</sup>

Detectable Warning No DW Necessary

Percent Deteriorated

0%

# GPS IMAGES AND COORDINATES HAVE BEEN REMOVED FROM THIS FILE FOR DATA PRIVACY





## **Scan Data**

| Metadata            |                                   |  |  |  |
|---------------------|-----------------------------------|--|--|--|
| Scan ID             | 199378                            |  |  |  |
| Inspection Date     | 2025-06-09                        |  |  |  |
| GPS Coordinates     |                                   |  |  |  |
| Accessibility Grade | 4                                 |  |  |  |
| Access Description  | Minor Barriers to Access<br>Found |  |  |  |
| Material            | Concrete                          |  |  |  |
| Detectable Warning  | No DW Necessary                   |  |  |  |
| Length Inspected    | 226 ft                            |  |  |  |
| Area Inspected      | 1092 ft <sup>2</sup>              |  |  |  |

| Condition Areas      |                                     |  |  |
|----------------------|-------------------------------------|--|--|
| Cracked Area         | 0 ft <sup>2</sup> 0 ft <sup>2</sup> |  |  |
| Deteriorated Area    | 1,092 ft <sup>2</sup>               |  |  |
| Panel Area           | 0%                                  |  |  |
| Percent Deteriorated |                                     |  |  |

| Slopes & Measurements |         |  |  |
|-----------------------|---------|--|--|
| Average Cross Slope   | 1.5%    |  |  |
| Max Cross Slope       | 4.1%    |  |  |
| Average Running Slope | 4.7%    |  |  |
| Max Running Slope     | 6.9%    |  |  |
| Average Width         | 55.0 in |  |  |
| Min Clear Width       | 37.0 in |  |  |

| Violations  |   |            |               |          |             |  |
|-------------|---|------------|---------------|----------|-------------|--|
| Cross Slope | • | Running SI | Running Slope |          | Clear Width |  |
| Extreme     | 0 | Extreme    | 0             | Extreme  | 0           |  |
| Severe      | 1 | Severe     | 0             | Severe   | 0           |  |
| Moderate    | 3 | Moderate   | 0             | Moderate | 2           |  |
| Minor       | 0 | Minor      | 0             | Minor    | 1           |  |



## **Annotated Raster Legend**

### **Ramp Violation Thresholds**

|              | Cross Slope |    | Run Slope |    | Width     |      |
|--------------|-------------|----|-----------|----|-----------|------|
| Severity     |             |    |           |    |           |      |
| Minor        | 2.5% - 3%   | cs | 8.3% - 9% | RS | 42" - 46" |      |
| Moderate     | 3% - 4%     | cs | 9% - 10%  | RS | 36" - 42" | CW   |
| Severe       | 4% - 6%     | cs | 10% - 12% | RS | 24" - 36" | CW   |
| Extreme      | 6+%         | cs | 12+%      | RS | 0" - 24"  | (CW) |
| Score Impact | High        |    | High      |    | High      |      |

### **Regions**



#### **Midblock Violation Thresholds**

|              | Cross Slope |    | Run Slope |    | Width     | Width |  |
|--------------|-------------|----|-----------|----|-----------|-------|--|
| Severity     |             |    |           |    |           |       |  |
| Minor        | 2.5% - 3%   | cs | 8.3% - 9% | RS | 42" - 46" |       |  |
| Moderate     | 3% - 4%     | cs | 9% - 10%  | RS | 36" - 42" | CW    |  |
| Severe       | 4% - 6%     | cs | 10% - 12% | RS | 24" - 36" | CW    |  |
| Extreme      | 6+%         | cs | 12+%      | RS | 0" - 24"  | (CW)  |  |
| Score Impact | High        |    | High      |    | High      |       |  |

#### **Manual Tags**

















