

EcoStruxure IT


UPS Assessment

Actions

UPS that needs replacement: 1
 UPS that need battery replacement: 0

Score distribution

3 devices with a low score



Optimizations

Higher temperature: 3
 Lower temperature: 7
 Balance phases: 0

UPS Load: Average

Security

Vulnerabilities Found: 4
 Low Severity Vuln: 3
 High Severity Vuln: 1

Devices ready for replacement

Device label	Model	Serial Number	Location	Age	Battery age	Score
Disco10kUPS01	Smart-UPS SRT 10...	QS1447142354	Rack1-1	11.5 Y	11.5 Y	untrusted
Disco10kUPS02	Smart-UPS SRT 10...	QS1447165909	Rack1-1	11.5 Y	11.5 Y	untrusted
Disco10kUPS07	Smart-UPS SRT 10...	QS1447135896	Rack1-3	11.5 Y	3 Y	untrusted
Disco10kUPS15	Smart-UPS SRT 10...	QS1447134985	Rack3-2	11.5 Y	8.5 Y	untrusted
Disco10kUPS16	Smart-UPS SRT 10...	QS1447132748	Rack3-2	11.5 Y	8.5 Y	untrusted
Disco10kUPS17	Smart-UPS SRT 10...	QS1447114579	Rack3-2	11.5 Y	8.5 Y	untrusted
Disco10kUPS22	Smart-UPS SRT 10...	QS1447153894	Rack4-1	11.5 Y	6 Y	untrusted
Disco10kUPS23	Smart-UPS SRT 10...	QS1447154986	Rack4-1	11.5 Y	6 Y	untrusted

This assessment is solely aimed at UPS in a non-redundant setup. We do a trend analysis on the daily average load of your UPS to predict the load in the future.

Load distribution
High load: 0
Medium load: 1
Low load: 7

Low load

Label	Model	Serial Number	Location	Load	Projected load
apcE19903	Smart-UPS 1500	AS00000003	No placement	18% (Apr 29)	21% (Jul 16)
apcE19905	Smart-UPS 1500	AS00000005	No placement	19% (Apr 29)	20% (Jul 16)
Disco10kUPS02	Smart-UPS SRT 10000	AS2242271411	Main Data Center	19% (Apr 29)	20% (Jun 15)
apcE19900	Smart-UPS 1500	AS00000000	No placement	20% (Apr 29)	22% (Jul 16)
Disco10kUPS01	Smart-UPS SRT 10000	QS1447172495	Rack1-1	20% (Apr 29)	21% (Jun 16)
apcE19902	Smart-UPS 1500	AS00000002	No placement	22% (Apr 29)	21% (Jul 16)
apcE19901	Smart-UPS 1500	AS00000001	No placement	23% (Apr 29)	20% (Jul 16)