








▲ Barbecue Pit



TOWER F (Premium Tower) **B+P1+P2+25 (27 floor levels)**
Terrace pergola work 100% completed.



completed.

completed

tank and diverter fixing complete

Completed. 19th F

- 2nd to 15th Floor balcony sliding doors completed.


- Basement 1: Putty work 50% completed.
- 2nd to 10th Floor coarse putty work completed.
- 2nd and 3rd Floor waterproofing in progress.
- 2nd to 23rd Floor GI wire pulling completed.




- Villa 9, 10, 11, 12, 13, 14, 15, 16, 17: Backyard structure work 100% completed.
 - Villa 12, 13, 14, 15, 16, 17: Waterproofing completed. Protection screed concrete in progress.
- 

A close-up photograph of a light-colored concrete wall. It features several rectangular openings or recessed sections, some of which appear to be window frames or ventilation ports. The texture of the concrete is visible, showing some minor imperfections and shadows.


- 31, 32, 33: Walkway excavation for plumbing completed.




- plastering 100% completed.



- Villa 56, 57, 58, 59, 60: First coat putty work in progress.





-



- 



TOWER D (Presidential Tower) B2+B1+P1+P2+29 (31 floor levels)

- 12th Floor slab completed. 13th Floor in progress.
- Basement 2: VDF 95% completed.
- Basement 1: VDF 100% completed.
- Basement 2: Putty work 70% completed.
- Basement 2: Putty work 60% completed.
- 2nd to 7th Floor GI wire pulling completed.
- 2nd to 7th Floor internal wall-grinding completed.
- 3rd Floor balcony railing work in progress.




TOWER B (Premium Tower) B+P1+P2+25 (27 floor levels)

- 6th Floor slab completed. 7th Floor slab in progress.
- Basement slab completed.
- Basement grade slab 95% completed.
- Parking 1 slab completed.
- Parking 2 slab completed.
- Parking driveway ramp concrete completed.
- Basement to Parking 2 internal wall-grinding completed.
- 2nd and 3rd Floor internal wall-grinding completed.






TOWER A (Premium Tower) B+P1+P2+25 (27 floor levels)

- 1st Floor slab work in progress.
- Basement slab completed.
- Basement grade slab 100% completed.
- Parking 1 slab completed.
- Parking 2 slab completed.
- Parking driveway ramps completed.
- Basement to Parking 2 internal grinding 90% completed.



CLUBHOUSE

- Ground Floor slab 100% completed.
- 1st Floor slab work in progress.
- Basement PCC work 100% completed.
- STP tank 100% completed.
- Rainwater Harvesting Tank 100% completed.




INTERNAL WORKS - TOWERS



▲ Internal walls putty work



▲ Internal tiling work



▲ Balcony waterproofing



▲ Balcony railings work



▲ Bathroom piping work

PHASE 1 - TERRACE WORKS



▲ Terrace parapet wall work in progress




▲ Terrace domestic water storage tank



▲ Terrace recycled flush water storage tank



▲ Terrace pergola work in progress




▲ C Tower terrace



▲ E Tower terrace



▲ F Tower terrace



▲ G Tower terrace

COMMON UTILITIES



▲ Staircase railings work




▲ Lift lobby area work in progress



▲ Basement VDF flooring



▲ Parking bays work in progress



▲ Common corridor tiling work




▲ Common corridor false-ceiling work




▲ F Tower Parking 2



▲ Stormwater drain work in progress




▲ East side compound wall work in progress



▲ A and B Towers parking ramp

OUTDOOR AMENITIES



▲ Community Space above parking ramp



▲ Outdoor Pergola work in progress



▲ Planter boxes work in progress

▲ Pet Park excavation work in progress

▲ Walking track work in progress

▲ Highpoint Pavilion structure work in progress

CURRENT PRICE STRUCTURE
@ Disha Pursuit of the Elements

Premium & Presidential Homes : ₹10,499/- (per sq.ft.) + 5% GST

Millennium Homes : **SOLD OUT**

Villas : **SOLD OUT**

WE WILL BE BACK WITH NEW UPDATES IN JANUARY 2027