

Vehicle History Report #: 62761092 Report Date: July 10, 2025 | 5:52 p.m. EDT Report Status: Complete

## 2018 HYUNDAI SANTA FE SE

Sport utility vehicle | 6 Cylinders | Gas KM8SNDHF3JU271425 Country of Assembly: Korea (South) Last Reported Odometer: 136,000 KM



No Accident/Damage Records Found



Last Registered In: Nova Scotia (Normal)



29 Service Records Found



No U.S. History Found



4 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca

(i)

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of July 10, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

## **Vehicle History Report**



# Accident/Damage

There are no accidents/damage reported on this vehicle.



## Registration

- This vehicle has been registered in the following locations in Canada (listed oldest to newest):
  - In the province of **Newfoundland** with **Normal** branding.
  - In the province of **Nova Scotia** with **Normal** branding.


We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



## **Service Records**

DATE	ODOMETER	SOURCE	DETAILS	
2018 Feb 28		PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  Recommended maintenance performed  Four tires balanced  Four tires mounted  Safety inspection performed  Tire condition and pressure checked	
2018 Apr 25		PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  Remote start installed Safety inspection performed Trailer hitch installed	
2018 May 10	17,711 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  • Remote start installed	
2018 Jun 30	21,205 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced	
2018 Aug 28	22,146 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  • Tire condition and pressure checked	
2018 Oct 3	28,981 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced Recommended maintenance performed Tire condition and pressure checked	
2019 Mar 14	35,389 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  Recommended maintenance performed	
2019 Apr 28	36,891 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced	
2019 May 25	36,893 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced	
2019 Jun 22	37,326 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  Recommended maintenance performed  Vehicle washed/detailed	
2019 Jul 22	39,748 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced	
2019 Aug 12	47,431 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  Maintenance inspection completed  Oil and filter changed	

	ODOMETER	SOURCE	DETAILS
2019 Oct 23	53,812 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  • Maintenance inspection completed  • Oil and filter changed
2019 Dec 20		PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  • Tire(s) replaced
2020 Jan 2	57,334 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  • Wipers/washers checked
2020 Mar 13	61,179 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  Maintenance inspection completed  Oil and filter changed
2020 Jun 26	69,770 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  Recommended maintenance performed
2020 Jul 28	72,316 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced
2020 Aug 18	75,074 KM	Gander Hyundai Gander, Newfoundland, Canada	Vehicle serviced
2020 Sep 8	78,419 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  • Maintenance inspection completed  • Oil and filter changed
2020 Oct 28	80,026 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced
2021 Jan 20	87,333 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  • Maintenance inspection completed  • Oil and filter changed
2021 Apr 28	96,248 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  • Maintenance inspection completed  • Oil and filter changed
2021 Jun 25	99,987 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  • Maintenance inspection completed
2021 Jul 30	104,998 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  Oil and filter changed
2021 Dec 3	114,025 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  Oil and filter changed
2022 Jan 21	116,055 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  • Maintenance inspection completed
2022 Mar 21	119,569 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Vehicle serviced  • Maintenance inspection completed
2022 Jul 7	126,997 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Vehicle serviced  • Oil and filter changed



Recall #: R0165 | Accessory Trailer Module Replacement Recall Date: 2020 Mar 05

### Recall Description

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness kit that could fail. Over time, moisture could enter the control module and cause a short circuit. Note: This recall only affects Hyundai Genuine Accessory trailer wiring harness kits that were manufactured by third parties and sold in Canada. These kits may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit could create a fire risk. This risk

remains even when the vehicle is parked. Corrective Actions: Hyundai will notify owners by mail and instruct you to inspect your vehicle to see if it has an affected trailer wiring harness installed. If it does, Hyundai will advise you to take your vehicle to a dealer to install a redesigned trailer wiring harness. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit **Hyundai's website**. (https://recall.hyundaicanada.com/)

Recall #: R0188 | Supplemental Canister Installation Recall Date: 2021 Apr 04

#### **Recall Description**

Environment Canada Recall ECR H003-21-002 Affected vehicles may exceed evaporative emissions standards. Dealers will install a supplemental evaporative canister.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)

Recall #: R0208 | ABS Control Module Recall Date: 2022 Nov 04

#### **Recall Description**

Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall does not affect vehicles equipped with smart cruise control (SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the ABS module and replace it, if necessary. The dealer will also replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit **Hyundai's website**. (https://recall.hyundaicanada.com/)

Recall #: C0525 - NC | Underbody Corrosion Recall Date: 2023 Dec 04

#### Recall Description

Issue: Hyundai Auto Canada is conducting a Special Service Campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. In extreme cases, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact HYUNDAI or visit Hyundai's website. (https://recall.hyundaicanada.com/)



### Stolen Vehicle Check

This vehicle is not actively declared stolen.



## **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS	
2017 Sep 26		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
		St. John's, Newfoundland,		First Owner Reported	
		Canada		Previous Use: Commercial	
2018 Feb 28		PARKWAY HYUNDAI	Service Record	Vehicle serviced	
		Corner Brook, Newfoundland,			
		Canada			
2018 Mar 1	16,134 KM	Independent Source	Odometer reading		
		Cornerbrook, NL, Canada			
2018 Apr 25		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
		Corner Brook, Newfoundland,		New Owner reported	
		Canada		•	

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Apr 25		PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2018 May 10	17,711 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2018 Jun 30	21,205 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2018 Aug 28	22,146 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2018 Sep 1		Motor Vehicle Dept. Corner Brook, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Oct 3	28,981 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2019 Mar 14	35,389 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2019 Apr 28	36,891 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2019 May 25	36,893 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2019 Jun 22	37,326 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2019 Jul 22	39,748 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2019 Aug 12	47,431 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2019 Oct 23	53,812 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2019 Dec 20		PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2020 Jan 2	57,334 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2020 Mar 5		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0165
2020 Mar 13	61,179 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2020 Apr 1		Motor Vehicle Dept. Corner Brook, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jun 26	69,770 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced

,				omero metery maperi
	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Jul 28	72,316 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2020 Aug 18	75,074 KM	Gander Hyundai Gander, Newfoundland, Canada	Service Record	Vehicle serviced
2020 Sep 8	78,419 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2020 Oct 28	80,026 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2021 Jan 20	87,333 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2021 Apr 1		Motor Vehicle Dept. Corner Brook, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Apr 4		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0188
2021 Apr 28	96,248 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2021 Jun 25	99,987 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2021 Jul 30	104,998 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2021 Dec 3	114,025 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2022 Jan 21	116,055 KM	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2022 Mar 21	119,569 КМ	PARKWAY HYUNDAI Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2022 Apr 1		Motor Vehicle Dept. Corner Brook, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Jul 7	126,997 KM	Meineke Car Care Center Corner Brook, Newfoundland, Canada	Service Record	Vehicle serviced
2022 Oct 24		Motor Vehicle Dept. Corner Brook, Newfoundland, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2022 Nov 4		HYUNDAI	Recall	Manufacturer Recall Issued Recall # R0208
2023 May 30	136,000 KM	Independent Source Truro, Nova Scotia, Canada	Odometer reading	
2023 Jun 26		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2023 Nov 10		Motor Vehicle Dept. Nova Scotia, Canada	Canadian Renewal	Registration Issued or Renewed
2023 Dec 4		HYUNDAI	Recall	Manufacturer Recall Issued Recall # C0525 - NC



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where is basis, and CARFAX Canada and its source data providers further expressly disclaimal ulwarranties, express or implied, including any warranties of members, accuracy, merchantability, merchantability, merchantability or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada and its source data providers further expressly disclaimal ulwarranties, express or implied, including any warranties of members, which is source data providers in the source data providers in the source data providers in the provider in the source data providers in the providers in the provider of a particular purpose regarding this report or its contents. Neither CARFAX Canada and its source data providers in the formation in the source data providers in the provider in the source of the provider of a provider of a provider and any express or implied, including any warranties, or desired within a report, including the accuracy thereof or any delay or failure to provide a report or any information contained within a report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle insection and test drive, to make a better decisions about your next used car. By obtaining, reviewing and using this vehicle th

© 2025 CARFAX Canada ULC. All rights reserved

