

BULLETIN NUMBER: SB-0019


DATE: 27/08/24

SUBJECT: Washing Sensitive Areas

INFORMATION ONLY

This is an information Bulletin advising the need to be careful when washing and cleaning machines.

The Gearbox sensor has 2 O-rings and sealing grease around it. Please be aware if the sensor or area close to has high pressure water directed at it or around this can lead to water leaking inside leading to possible degradation of internal components.



Any further support, please contact your Bredal Representative.