



SERVICE INFORMATION, 23.05.2017

Problems when installing wire clamps for DT1 (50340)

Please follow this guide if the clamps are very hard to push in place.



Here you can see a before and after illustration.

The clamps should now be possible to mount without using excessive force.

