


Due Diligence					
Report Date	11/08/2025	Inspected By	KIM	Supervisor	RONALD
Y.O.M	2019	Make & Model	TOYOTA JIS0	Model Code	1GD
Reg. No. (if appl.)	—	VIN Number	GDJ150-0036432	Engine No.	—
Mileage (Km)	69036	Mileage Verified	✓	Use Country	JAPAN
Logbook Ver. (If appl.)	—	Previous Owners	—	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	✓ / ✓ / ✓	Original Handbook	—	Spare Key	✓
Service History Ver.	—	Last Service (Km)	—	Next Service (Km)	69036
Body/Exterior Inspection					
		D = Dent	General Comments: MINOR SCRATCHES		
		S = Scratch			
		M = Missing Trim			
		RP = Repainted			
		SR = Surface Rust	Structural & Underbody Comments: CLEAN NO RUST/ CORROSION		
		R = Moderate Rust			
		CR = Corrosion			
		C = Crack / Chip			
Exterior Grade (%)		80%			
Structural & Underbody Grade (%)		80%			
Interior Inspection					
Upholstery	✓	Dash & Plastics	✓	Smoked In	NO
Seats Fuct. (inc belts)	✓	Floor Mats	✓	Interior Grade (%)	80%
Comments:					
Mechanical Inspection					
Exterior Lights	✓	Wipers	✓	Tyre Tread Depth	COMMENTS
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	✓
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO	Eng. Oil Leaks	NO
Cooling System Test	✓	Heat Exchangers	✓	Other leaks	NO
Fuses & relays	✓	Fluids	✓	Exhaust System	✓
Shocks & Springs	✓	Sus. Bushings	✓	Boots & Shafts	✓
Ball Joints / Tie Rods	✓	Column & Rack	✓	Hubs & W. Brgs	✓
Rubber Mountings	✓	Brake Pads (F/R)	80% / 80%	Brake Discs (F/R)	90% / 90%
Comments: TIRES ARE OLD & CRACKED				Modifications	Y / (N)
				Mech Grade (%)	90%
Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	NO
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L. Range	✓ / ✓	Diff Locks(s)	✓ CENTRAL	Steering Feedback	✓
Comments:					
Recommended Repairs and/or Final Comments					
SERVICE NEW TIRES					
WA Final Assessment / %					WA Warranty
Practically As-new/	Excellent / 85%	Good. /	Fair /	Needs Work /	12-Months

1. 100

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000