


Due Diligence									
Report Date	<u>26/01/2026</u>	Inspected By	<u>MCKEAL</u>	Supervisor	<u>RONAK</u>				
Y.O.M	<u>2018</u>	Make & Model	<u>MITSUBISHI PAJERO</u>	Model Code	<u>4M41</u>				
Reg. No. (if appl.)	<u>UNREGISTERED</u>	VIN Number	<u>V98W-1100591</u>	Engine No.	<u>—</u>				
Mileage (Km)	<u>64500km</u>	Mileage Verified	<input checked="" type="checkbox"/>	Use Country	<u>JAPAN</u>				
Logbook Ver. (If appl.)	<u>—</u>	Previous Owners	<u>—</u>	Priv. / comm	<u>PRIVATE</u>				
Spare Tyre, Jack, Tools	<u>✓/✓/✓</u>	Original Handbook	<u>—</u>	Spare Key	<input checked="" type="checkbox"/>				
Service History Ver.	<u>—</u>	Last Service (Km)	<u>—</u>	Next Service (Km)	<u>64500km</u>				
Body/Exterior Inspection									
		D = Dent	General Comments: <u>VERY MINOR SCRATCHES</u>						
		S = Scratch							
		M = Missing Trim	Structural & Underbody Comments: <u>UNDERSEALED</u> <u>NO VISIBLE RUST</u>						
		RP = Repainted							
		SR = Surface Rust	<table border="1"> <tr> <td>Exterior Grade (%)</td> <td><u>85%</u></td> </tr> <tr> <td>Structural &amp; Underbody Grade (%)</td> <td><u>85%</u></td> </tr> </table>			Exterior Grade (%)	<u>85%</u>	Structural & Underbody Grade (%)	<u>85%</u>
		Exterior Grade (%)				<u>85%</u>			
Structural & Underbody Grade (%)	<u>85%</u>								
R = Moderate Rust									
CR = Corrosion									
C = Crack / Chip									
Interior Inspection									
Upholstery	<input checked="" type="checkbox"/>	Dash & Plastics	<input checked="" type="checkbox"/>	Smoked In	<u>NO</u>				
Seats Fuct. (inc belts)	<input checked="" type="checkbox"/>	Floor Mats	<input checked="" type="checkbox"/>	Interior Grade (%)	<u>85%</u>				
Comments: <u>CLEAN INTERIOR</u>									
Mechanical Inspection									
Exterior Lights	<input checked="" type="checkbox"/>	Wipers	<input checked="" type="checkbox"/>	Tyre Tread Depth	<u>✓NEW TIRES</u>				
Elec. Interior Equip.	<input checked="" type="checkbox"/>	Infotainment	<input checked="" type="checkbox"/>	HVAC System	<input checked="" type="checkbox"/>				
Eng. Ancillary Cpts.	<input checked="" type="checkbox"/>	Eng. Blowby	<u>NO</u>	Eng. Oil Leaks	<u>COMMENTS</u>				
Cooling System Test	<input checked="" type="checkbox"/>	Heat Exchangers	<input checked="" type="checkbox"/>	Other leaks	<u>NO</u>				
Fuses & relays	<input checked="" type="checkbox"/>	Fluids	<input checked="" type="checkbox"/>	Exhaust System	<input checked="" type="checkbox"/>				
Shocks & Springs	<input checked="" type="checkbox"/>	Sus. Bushings	<input checked="" type="checkbox"/>	Boots & Shafts	<input checked="" type="checkbox"/>				
Ball Joints / Tie Rods	<input checked="" type="checkbox"/>	Column & Rack	<input checked="" type="checkbox"/>	Hubs & W. Brgs	<input checked="" type="checkbox"/>				
Rubber Mountings	<input checked="" type="checkbox"/>	Brake Pads (F/R)	<u>80% / 80%</u>	Brake Discs (F/R)	<u>80% / 80%</u>				
Comments: <u>MINOR SEAPING FROM TOP COVER GASKET</u>				Modifications	<u>Y / (N)</u>				
				Mech Grade (%)	<u>85%</u>				
Road Test Report									
Engine Start Up	<input checked="" type="checkbox"/>	Braking	<input checked="" type="checkbox"/>	NVH	<u>NO</u>				
Engine Perf. & Acc.	<input checked="" type="checkbox"/>	Gear Shifting	<input checked="" type="checkbox"/>	Warning Lights	<u>NO</u>				
4WD / L. Range	<u>✓/✓</u>	Diff Locks(s)	<u>✓CENTRAL</u>	Steering Feedback	<input checked="" type="checkbox"/>				
Comments:									
Recommended Repairs and/or Final Comments									
<u>CLEAN LOW MILEAGE CAR</u>									
WA Final Assessment / %					WA Warranty				
Practically As-new/	<u>Excellent</u> <u>85%</u>	Good. /	Fair /	Needs Work /	<u>2-MONTHS</u>				

