

Veh. Ref. No. TY 3908

**Due Diligence**

Report Date	<u>05/03/2020</u>	Inspected By	<u>RONAK</u>	Supervisor	<u>RONAK</u>
Y.O.M	<u>2018</u>	Make & Model	<u>TOYOTA HILUX</u>	Model Code	
Reg. No. (if appl.)	<u>—</u>	VIN Number	<u>GUN125-3909084</u>	Engine No.	<u>—</u>
Mileage (Km)	<u>61955km</u>	Mileage Verified	<u>—</u>	Use Country	<u>JAPAN</u>
Logbook Ver. (If appl.)	<u>—</u>	Previous Owners	<u>—</u>	(Priv./) comm	<u>PRIVATE</u>
Spare Tyre, Jack, Tools	<u>✓/—/—</u>	Original Handbook	<u>3</u>	Spare Key	<u>2</u>
Service History Ver.	<u>—</u>	Last Service (Km)	<u>—</u>	Next Service (Km)	<u>61955km</u>

**Body/Exterior Inspection**

	D = Dent	<b>General Comments:</b> <u>FRONT BUMPER REPAINTED</u> <u>MINOR SCRATCHES</u> <u>NO DENTS</u>
	S = Scratch	
	M = Missing Trim	
	RP = Repainted	<b>Structural &amp; Underbody Comments:</b> <u>VERY MINOR SURFACE RUST</u>
	SR = Surface Rust	
	R = Moderate Rust	
CR = Corrosion		
C = Crack / Chip	<b>Exterior Grade (%)</b> <u>80%</u> <b>Structural &amp; Underbody Grade (%)</b> <u>85%</u>	

**Interior Inspection**

Upholstery	<u>✓</u>	Dash & Plastics	<u>✓</u>	Smoked In	<u>NO</u>
Seats Fuct. (inc belts)	<u>✓</u>	Floor Mats	<u>✓ RUBBER</u>	Interior Grade (%)	<u>85%</u>
Comments: <u>CLEAN &amp; COMPLETE INTERIOR</u>					

**Mechanical Inspection**

Exterior Lights	<u>✓</u>	Wipers	<u>✓</u>	Tyre Tread Depth	<u>✓ 80%</u>
Elec. Interior Equip.	<u>✓</u>	Infotainment	<u>✓</u>	HVAC System	<u>✓</u>
Eng. Ancillary Cpts.	<u>✓</u>	Eng. Blowby	<u>NO</u>	Eng. Oil Leaks	<u>NO</u>
Cooling System Test	<u>✓</u>	Heat Exchangers	<u>✓</u>	Other leaks	<u>NO</u>
Fuses & relays	<u>✓</u>	Fluids	<u>✓</u>	Exhaust System	<u>✓</u>
Shocks & Springs	<u>COMMENT</u>	Sus. Bushings	<u>✓</u>	Boots & Shafts	<u>✓</u>
Ball Joints / Tie Rods	<u>✓</u>	Column & Rack	<u>✓</u>	Hubs & W. Brgs	<u>✓</u>
Rubber Mountings	<u>✓</u>	Brake Pads (F/R)	<u>50% / 80%</u>	Brake Discs (F/R)	<u>— / —</u>
Comments: <u>SPARE TYRE DIFFERENT BRAND TO THE REST &amp; WORN</u> <u>— REAR</u>				Modifications	<u>Y / (N)</u>
				Mech Grade (%)	

**Road Test Report**

Engine Start Up	<u>✓</u>	Braking	<u>✓</u>	NVH	<u>NO</u>
Engine Perf. & Acc.	<u>✓</u>	Gear Shifting	<u>✓</u>	Warning Lights	<u>NO</u>
4WD / L. Range	<u>✓/✓</u>	Diff Locks(s)	<u>✓ REAR</u>	Steering Feedback	<u>✓</u>
Comments:					

**Recommended Repairs and/or Final Comments**

TONNAVE COVER ON PICK-UP BED

WA Final Assessment / %					WA Warranty
Practically As-new/	Excellent /	Good <u>185%</u>	Fair /	Needs Work /	