

Veh. Ref. No. RR 2508

Due Diligence					
Report Date	<u>25/02/2026</u>	Inspected By	<u>MICHAEL</u>	Supervisor	<u>RONAK</u>
Y.O.M	<u>2018</u>	Make & Model	<u>RANGE ROVER</u>	Model Code	<u>AUTODGRAPHY</u>
Reg. No. (if appl.)	<u>KDD 220L</u>	VIN Number	<u>SALGADAEJ507876</u>	Engine No.	<u>18032431022508PS</u>
Mileage (Km)	<u>63,173km</u>	Mileage Verified	<input checked="" type="checkbox"/>	Use Country	<u>KENYA</u>
Logbook Ver. (If appl.)	<input checked="" type="checkbox"/>	Previous Owners	<u>1</u>	Priv. / comm	<u>PRIVATE</u>
Spare Tyre, Jack, Tools	<u>✓/✓/✓</u>	Original Handbook		Spare Key	<input checked="" type="checkbox"/>
Service History Ver.	<u>-</u>	Last Service (Km)	<u>57,500km</u>	Next Service (Km)	<u>65000km</u>

Body/Exterior Inspection		
	D = Dent	General Comments: <u>WHEELS CURBED</u> <u>VERY CLEAN</u> <u>MINOR SCRATCHES</u> <u>FRONT BUMPER REPAINTED</u>
	S = Scratch	
	M = Missing Trim	
	RP = Repainted	Structural & Underbody Comments: <u>CLEAN, NO RUST</u>
	SR = Surface Rust	
	R = Moderate Rust	
	CR = Corrosion	
C = Crack / Chip	Exterior Grade (%)	<u>85%</u>
Structural & Underbody Grade (%)		<u>85%</u>

Interior Inspection			
Upholstery	<input checked="" type="checkbox"/>	Dash & Plastics	<input checked="" type="checkbox"/>
Seats Fuct. (inc belts)	<input checked="" type="checkbox"/>	Floor Mats	<input checked="" type="checkbox"/>
Smoked In		<u>NO</u>	
Interior Grade (%)		<u>85%</u>	
Comments: <u>VERY CLEAN, MINOR WEAR ON DRIVER SEAT & DOOR CARDS</u>			

Mechanical Inspection					
Exterior Lights	<input checked="" type="checkbox"/>	Wipers	<input checked="" type="checkbox"/>	Tyre Tread Depth	<u>✓ 70% AIT</u>
Elec. Interior Equip.	<input checked="" type="checkbox"/>	Infotainment	<input checked="" type="checkbox"/>	HVAC System	<input checked="" type="checkbox"/>
Eng. Ancillary Cpts.	<input checked="" type="checkbox"/>	Eng. Blowby	<u>NO</u>	Eng. Oil Leaks	<u>NO</u>
Cooling System Test	<input checked="" type="checkbox"/>	Heat Exchangers	<input checked="" type="checkbox"/>	Other leaks	<u>NO</u>
Fuses & relays	<input checked="" type="checkbox"/>	Fluids	<input checked="" type="checkbox"/>	Exhaust System	<input checked="" type="checkbox"/>
Shocks & Springs	<input checked="" type="checkbox"/>	Sus. Bushings	<input checked="" type="checkbox"/>	Boots & Shafts	<input checked="" type="checkbox"/>
Ball Joints / Tie Rods	<input checked="" type="checkbox"/>	Column & Rack	<input checked="" type="checkbox"/>	Hubs & W. Brgs	<input checked="" type="checkbox"/>
Rubber Mountings	<input checked="" type="checkbox"/>	Brake Pads (F/R)	<u>80% / 80%</u>	Brake Discs (F/R)	<u>80% / 80%</u>
Comments: <u>TIRE TREAD DEPTH AT 70% BUT REAR RIGHT TIRE CHIPPED SIDEWALL</u>				Modifications	<u>Y / (N)</u>
				Mech Grade (%)	<u>85%</u>

Road Test Report					
Engine Start Up	<input checked="" type="checkbox"/>	Braking	<input checked="" type="checkbox"/>	NVH	<u>NO</u>
Engine Perf. & Acc.	<input checked="" type="checkbox"/>	Gear Shifting	<input checked="" type="checkbox"/>	Warning Lights	<u>NO</u>
4WD / L. Range	<u>✓/✓</u>	Diff Locks(s)	<u>-</u>	Steering Feedback	<input checked="" type="checkbox"/>
Comments:					

Recommended Repairs and/or Final Comments
LOW MILEAGE, CLEAN CAR

WA Final Assessment / %				WA Warranty
Practically As-new/	<u>Excellent / 85%</u>	Good. /	Fair /	Needs Work /
				<u>-</u>