

Due Diligence					
Report Date	10/03/2026	Inspected By	MICHAEL	Supervisor	RONAK
Y.O.M	2005	Make & Model	TOYOTA PRADO 120	Model Code	1GR
Reg. No. (if appl.)	KBT 328Y	VIN Number	GRJ285027396	Engine No.	1GR5156335
Mileage (Km)	126,396km	Mileage Verified	✓	Use Country	KENYA
Logbook Ver. (If appl.)	✓	Previous Owners	2	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	✓/✓/✓	Original Handbook	—	Spare Key	✓
Service History Ver.	—	Last Service (Km)	126,160km	Next Service (Km)	132,660km
Body/Exterior Inspection					
		D = Dent	General Comments: MINOR SCRATCHES		
		S = Scratch			
		M = Missing Trim			
		RP = Repainted			
		SR = Surface Rust	Structural & Underbody Comments: CLEAN NO RUST		
		R = Moderate Rust			
CR = Corrosion					
C = Crack / Chip					
Exterior Grade (%)			75%		
Structural & Underbody Grade (%)			75%		
Interior Inspection					
Upholstery	✓	Dash & Plastics	✓	Smoked In	NO
Seats Fuct. (inc belts)	✓	Floor Mats	✓	Interior Grade (%)	75%
Comments: SEAT COVERS					
Mechanical Inspection					
Exterior Lights	✓	Wipers	✓	Tyre Tread Depth	✓ 70%
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	✓
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO	Eng. Oil Leaks	NO
Cooling System Test	✓	Heat Exchangers	✓	Other leaks	NO
Fuses & relays	✓	Fluids	✓	Exhaust System	✓
Shocks & Springs	✓	Sus. Bushings	✓	Boots & Shafts	COMMENTS
Ball Joints / Tie Rods	✓	Column & Rack	✓	Hubs & W. Brgs	✓
Rubber Mountings	✓	Brake Pads (F/R)	70% / 70%	Brake Discs (F/R)	80% / 80%
Comments: BULL BAR ! SPOT LIGHTS ROOF RACK ! ROBS MAGIC COIL SPRINGS ! XGS REAR ER GAS				Modifications	Ⓢ / Ⓢ
				Mech Grade (%)	75%
Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	NO
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L. Range	✓/✓	Diff Locks(s)	—	Steering Feedback	✓
Comments:					
Recommended Repairs and/or Final Comments					
FRONT LHS INNER CV BOOT TORN FRONT CV'S NEED GREASING VERY CLEAN FOR MILEAGE & AGE					
WA Final Assessment / %					WA Warranty
Practically As-new/	Excellent /	Good / 75%	Fair /	Needs Work /	—