

Due Diligence					
Report Date	22/04/2025	Inspected By	MICHAEL	Supervisor	RONAK
Y.O.M	2003	Make & Model	TOYOTA LUDG	Model Code	VX
Reg. No. (if appl.)	KBN 776R	VIN Number	U2J100-0143697	Engine No.	-
Mileage (Km)	253,818km	Mileage Verified	-	Use Country	KENYA
Logbook Ver. (If appl.)	✓	Previous Owners	TBC	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	✓/✓/—	Original Handbook	✓	Spare Key	TBC
Service History Ver.	—	Last Service (Km)	—	Next Service (Km)	TBC

Body/Exterior Inspection		
	D = Dent	General Comments: MINOR SCRATCHES & DENT MISSING TRIM ON ROOF RAIL
	S = Scratch	
	M = Missing Trim	Structural & Underbody Comments: NO RUST / CORROSION
	RP = Repainted	
	SR = Surface Rust	
	R = Moderate Rust	
	CR = Corrosion	
C = Crack / Chip		
Exterior Grade (%)		70%
Structural & Underbody Grade (%)		70%

Interior Inspection					
Upholstery	✓ SEAT COVERS	Dash & Plastics	✓	Smoked In	NO
Seats Fuct. (inc belts)	✓	Floor Mats	✓ SET	Interior Grade (%)	70%
Comments:					

Mechanical Inspection						
Exterior Lights	COMMENTS	Wipers	✓	Tyre Tread Depth	✓ 90%	
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	✓	
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO	Eng. Oil Leaks	NO	
Cooling System Test	✓	Heat Exchangers	✓	Other leaks	NO	
Fuses & relays	✓	Fluids	✓	Exhaust System	✓	
Shocks & Springs	✓	Sus. Bushings	✓	Boots & Shafts	COMMENTS	
Ball Joints / Tie Rods	COMMENTS	Column & Rack	COMMENTS	Hubs & W. Brgs	✓	
Rubber Mountings	✓	Brake Pads (F/R)	85% / 85%	Brake Discs (F/R)	80% / 80%	
Comments: MISFIRE - SPARK PLUGS REPLACEMENT TIRE ROD ENDS WORN RACK END BOOTS WORN - POSSIBLY RACK ENDS WORN			DRIVE SHAFT BUSHES FORN (CV) BULBAR INDICATOR BUSH		Modifications	Y / N
					Mech Grade (%)	70%

Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	MISFIRE
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L. Range	✓/✓	Diff Locks(s)	—	Steering Feedback	✓
Comments:					

Recommended Repairs and/or Final Comments	
BULBAR POWER BRAKE BRAKE KIT PROFENDER REMOTE RESERVE SHOCKS	NOT ORIGINAL ENGINE - ENGINE RESULT

WA Final Assessment / %				WA Warranty	
Practically As-new/	Excellent /	Good. /	(Fair) / 70%	Needs Work /	—

