

Due Diligence					
Report Date	12/05/2026	Inspected By	WALEED	Supervisor	RONAK
Y.O.M	1988	Make & Model	TOYOTA LC71	Model Code	SL
Reg. No. (if appl.)	KAM 375C	VIN Number	LJ71-0004184	Engine No.	SL-5007737
Mileage (Km)	330,000km	Mileage Verified	✓	Use Country	KENYA
Logbook Ver. (If appl.)	✓	Previous Owners	2	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	✓/✓/✓	Original Handbook	-	Spare Key	✓
Service History Ver.	-	Last Service (Km)	322000km	Next Service (Km)	326,000km

Body/Exterior Inspection					
	D = Dent	General Comments: MINOR SCRATCHES SLIGHT PAINT PEEL			
	S = Scratch				
	M = Missing Trim	Structural & Underbody Comments: MINOR SURFACE RUST			
	RP = Repainted				
	SR = Surface Rust				
R = Moderate Rust	<table border="1"> <tr> <td>Exterior Grade (%)</td> <td>70%</td> </tr> <tr> <td>Structural & Underbody Grade (%)</td> <td>70%</td> </tr> </table>	Exterior Grade (%)	70%	Structural & Underbody Grade (%)	70%
Exterior Grade (%)		70%			
Structural & Underbody Grade (%)		70%			
CR = Corrosion					
C = Crack / Chip					

Interior Inspection					
Upholstery	✓ SEAT COVERS	Dash & Plastics	✓	Smoked In	NO
Seats Fuct. (inc belts)	✓	Floor Mats	✓	Interior Grade (%)	70%
Comments: CLEAN & RELATIVELY COMPLETE INTERIOR					

Mechanical Inspection					
Exterior Lights	✓	Wipers	✓	Tyre Tread Depth	✓ 80%
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	-
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO	Eng. Oil Leaks	COMMENT
Cooling System Test	✓ NEW RADIATOR	Heat Exchangers	✓	Other leaks	COMMENT
Fuses & relays	✓	Fluids	✓	Exhaust System	✓
Shocks & Springs	✓	Sus. Bushings	COMMENT	Boots & Shafts	✓
Ball Joints / Tie Rods	✓	Column & Rack	✓	Hubs & W. Brgs	COMMENT
Rubber Mountings	✓	Brake Pads (F/R)	70% / -	Brake Discs (F/R)	80% / -
Comments: POWER STEERING PUMP LEAK LHS SUVIC HUB LEAK RHS FRONT WHEEL SHAKING PLAY				FRONT & REAR WANK SHAKES CRACK PAINT TRANSFER CASE FRONT PANHARD BUSHES WORN	
				Modifications	(B) / N
				Mech Grade (%)	70%

Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	NO
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L Range	✓ / ✓	Diff Locks(s)	-	Steering Feedback	✓
Comments:					

Recommended Repairs and/or Final Comments		
OME COILS FRONT & REAR	FRONT RUNNER RACK	ROOF RATCH
XCEL SHOCKS	REAR DRIVING	SPOTLIGHTS
NEW REAR RADIATOR	REAR DOOR TABLE	NEW BATTERY
OME STEERING DAMPER	REAR POWER POINT	
REVERSE CAMERA / DASH CAM	MONO STEERING WHEEL	

WA Final Assessment / %				WA Warranty	
Practically As-new/	Excellent /	Good / 70%	Fair /	Needs Work /	✓