


Due Diligence					
Report Date	20/08/2026	Inspected By	RONAK	Supervisor	RONAK
Y.O.M	2019	Make & Model	SUBARU OUTBACK	Model Code	J20
Reg. No. (if appl.)	—	VIN Number	B39 056514	Engine No.	—
Mileage (Km)	49692km	Mileage Verified	✓	Use Country	JAPAN
Logbook Ver. (if appl.)	—	Previous Owners	—	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	/ /	Original Handbook	—	Spare Key	TBC
Service History Ver.	—	Last Service (Km)	—	Next Service (Km)	49692km

Body/Exterior Inspection		
	D = Dent	General Comments: MINOR SCRATCHES REPAINTED PANELS
	S = Scratch	
	M = Missing Trim	
	RP = Repainted	Structural & Underbody Comments: NO RUST / CORROSION
	SR = Surface Rust	
	R = Moderate Rust	
	CR = Corrosion	
	C = Crack / Chip	
Exterior Grade (%)		80%
Structural & Underbody Grade (%)		80%

Interior Inspection					
Upholstery	✓	Dash & Plastics	✓	Smoked In	NO
Seats Fct. (inc belts)	✓	Floor Mats	✓	Interior Grade (%)	

Comments: MINOR WEAR ON STEERING WHEEL & CENTER CONSOLE

Mechanical Inspection					
Exterior Lights	✓	Wipers	✓	Tyre Tread Depth	✓ 60%
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	✓
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO	Eng. Oil Leaks	NO
Cooling System Test	✓	Heat Exchangers	✓	Other leaks	NO
Fuses & relays	✓	Fluids	✓	Exhaust System	✓
Shocks & Springs	✓	Sus. Bushings	✓	Boots & Shafts	✓
Ball Joints / Tie Rods	✓	Column & Rack	✓	Hubs & W. Brgs	✓
Rubber Mountings	✓	Brake Pads (F/R)	60% / 50%	Brake Discs (F/R)	80% / 80%
Comments:				Modifications	Y / N
				Mech Grade (%)	80%

Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	NO
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L. Range	AWD / —	Diff Lock(s)	—	Steering Feedback	✓
Comments:					

Recommended Repairs and/or Final Comments					
CLEAN LOW MILEAGE CAR					

WA Final Assessment / %				WA Warranty	
Practically As-new /	Excellent /	Good / 80%	Fair /	Needs Work /	TBC