


Due Diligence					
Report Date	25/08/2026	Inspected By	RONAK	Supervisor	RONAK
Y.O.M	2019	Make & Model	MAZDA CX-8	Model Code	
Reg. No. (if appl.)	—	VIN Number	KG2P-300657	Engine No.	—
Mileage (Km)	68334km	Mileage Verified	✓	Use Country	JAPAN
Logbook Ver. (If appl.)	—	Previous Owners	—	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	- / ✓ ✓	Original Handbook	—	Spare Key	TBC
Service History Ver.	—	Last Service (Km)	—	Next Service (Km)	68334km
Body/Exterior Inspection					
		D = Dent	General Comments: MINOR SCRATCHES		
		S = Scratch			
		M = Missing Trim			
		RP = Repainted	Structural & Underbody Comments: VERY MINOR SURFACE RUST		
		SR = Surface Rust			
		R = Moderate Rust			
CR = Corrosion					
C = Crack / Chip					
			Exterior Grade (%)	80%	
			Structural & Underbody Grade (%)	80%	
Interior Inspection					
Upholstery	✓	Dash & Plastics	✓	Smoked In	NO
Seats Fuct. (inc belts)	✓	Floor Mats	✓	Interior Grade (%)	80%
Comments: CLEAN & COMPLETE INTERIOR					
Mechanical Inspection					
Exterior Lights	✓	Wipers	✓	Tyre Tread Depth	70% WINTER TIRES
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	✓
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO	Eng. Oil Leaks	NO
Cooling System Test	✓	Heat Exchangers	✓	Other leaks	NO
Fuses & relays	✓	Fluids	✓	Exhaust System	✓
Shocks & Springs	✓	Sus. Bushings	COMMENT	Boots & Shafts	✓
Ball Joints / Tie Rods	✓	Column & Rack	✓	Hubs & W. Brgs	✓
Rubber Mountings	✓	Brake Pads (F/R)	60% / 60%	Brake Discs (F/R)	70% / 70%
Comments: FRONT LOWER ARM BIG BUSHES HAVE SLIGHT TEAR				Modifications	Y / N
				Mech Grade (%)	80%
Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	NO
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L. Range	✓ / ✗	Diff Locks(s)	✗	Steering Feedback	✓
Comments: AWS					
Recommended Repairs and/or Final Comments					
WINTER TIRES - REPLACE					
WA Final Assessment / %					WA Warranty
Practically As-new/	Excellent /	Good / 80%	Fair /	Needs Work /	TBC