


Due Diligence

Report Date	<u>25/08/2026</u>	Inspected By	<u>GODFREY</u>	Supervisor	<u>RONAK</u>
Y.O.M	<u>2009</u>	Make & Model	<u>SUBARU OUTBACK</u>	Model Code	<u>EZ36</u>
Reg. No. (if appl.)	<u>KCD 867X</u>	VIN Number	<u>BRF-002549</u>	Engine No.	<u>EZ36-U322331</u>
Mileage (Km)	<u>93572km</u>	Mileage Verified	<u>✓</u>	Use Country	<u>KENYA</u>
Logbook Ver. (If appl.)	<u>✓</u>	Previous Owners	<u>0</u>	Priv. / comm	<u>PRIVATE</u>
Spare Tyre, Jack, Tools	<u>✓ / ✓ / ✓</u>	Original Handbook	<u>—</u>	Spare Key	<u>TBC</u>
Service History Ver.	<u>—</u>	Last Service (Km)	<u>85495km</u>	Next Service (Km)	<u>95495km</u>

Body/Exterior Inspection



D = Dent	General Comments: <u>MINOR SCRATCHES & DENT</u>
S = Scratch	
M = Missing Trim	
RP = Repainted	
SR = Surface Rust	Structural & Underbody Comments: <u>NO RUST / CORROSION</u>
R = Moderate Rust	
CR = Corrosion	
C = Crack / Chip	
Exterior Grade (%)	<u>70%</u>
Structural & Underbody Grade (%)	<u>70%</u>

Interior Inspection

Upholstery	<u>SEAT COVERS</u>	Dash & Plastics	<u>✓</u>	Smoked In	<u>NO</u>
Seats Fuct. (inc belts)	<u>✓</u>	Floor Mats	<u>✓</u>	Interior Grade (%)	<u>70%</u>

Comments: MINOR SCRATCHES ON DASH & PLASTICS

Mechanical Inspection

Exterior Lights	<u>✓</u>	Wipers	<u>✓</u>	Tyre Tread Depth	<u>OLD & CRACKING</u>
Elec. Interior Equip.	<u>✓</u>	Infotainment	<u>✓</u>	HVAC System	<u>✓</u>
Eng. Ancillary Cpts.	<u>✓</u>	Eng. Blowby	<u>NO</u>	Eng. Oil Leaks	<u>NO</u>
Cooling System Test	<u>✓</u>	Heat Exchangers	<u>✓</u>	Other leaks	<u>NO</u>
Fuses & relays	<u>✓</u>	Fluids	<u>✓</u>	Exhaust System	<u>✓</u>
Shocks & Springs	<u>✓</u>	Sus. Bushings	<u>COMMENT</u>	Boots & Shafts	<u>✓</u>
Ball Joints / Tie Rods	<u>✓</u>	Column & Rack	<u>COMMENT</u>	Hubs & W. Brgs	<u>✓</u>
Rubber Mountings	<u>✓</u>	Brake Pads (F/R)	<u>20% / 20%</u>	Brake Discs (F/R)	<u>70% / 70%</u>
Comments: <u>FRONT & REAR STABILIZER DISCS WORN / FRONT & REAR BRAKE PADS WORN</u>				Modifications	<u>Y / (N)</u>
<u>REAR TRAILING ARM BUSHES WORN</u>				Mech Grade (%)	<u>70%</u>
<u>SERVICE</u>					

Road Test Report

Engine Start Up	<u>✓</u>	Braking	<u>—</u>	NVH	<u>NO</u>
Engine Perf. & Acc.	<u>✓</u>	Gear Shifting	<u>✓</u>	Warning Lights	<u>NO</u>
4WD / L. Range	<u>✓ / —</u>	Diff Locks(s)	<u>—</u>	Steering Feedback	<u>COMMENT</u>

Comments:

Recommended Repairs and/or Final Comments

STEERING RACK HAS PLAY - REPLACE

WA Final Assessment / %

WA Warranty

Practically As-new /	Excellent /	<u>Good</u> / <u>70%</u>	Fair /	Needs Work /	<u>—</u>
----------------------	-------------	--------------------------	--------	--------------	----------