


Due Diligence					
Report Date	26/08/2026	Inspected By	MICHAEL GOODWIN	Supervisor	RONAK
Y.O.M	2020	Make & Model	MITSUBISHI PAJERO	Model Code	4M41
Reg. No. (if appl.)	KDZ119B	VIN Number	JMFLV99NLSJ002864	Engine No.	4M41UAV6369
Mileage (Km)	75331 km	Mileage Verified	✓	Use Country	KENYA
Logbook Ver. (If appl.)	✓	Previous Owners	0	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	✓ / ✓ / ✓	Original Handbook	—	Spare Key	✓
Service History Ver.	—	Last Service (Km)	74741 km	Next Service (Km)	79741 km

Body/Exterior Inspection	
	D = Dent S = Scratch M = Missing Trim RP = Repainted SR = Surface Rust R = Moderate Rust CR = Corrosion C = Crack / Chip
	General Comments: SCRATCHES & DENTS VISIBLE CAR IS WRAPPED PAINT CONDITION UNKNOWN
	Structural & Underbody Comments: CLEAN NO RUST / CORROSION
	Exterior Grade (%) 70%
	Structural & Underbody Grade (%) 70%

Interior Inspection			
Upholstery	✓	Dash & Plastics	✓
Seats Fuct. (inc belts)	✓	Floor Mats	✓
Comments: SEAT COVERS		Smoked In	NO
		Interior Grade (%)	70%

Mechanical Inspection					
Exterior Lights	COMMENT	Wipers	✓	Tyre Tread Depth	60%
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	✓
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO	Eng. Oil Leaks	NO
Cooling System Test	✓	Heat Exchangers	✓	Other leaks	NO
Fuses & relays	✓	Fluids	✓	Exhaust System	✓
Shocks & Springs	✓	Sus. Bushings	COMMENT	Boots & Shafts	✓
Ball Joints / Tie Rods	✓	Column & Rack	✓	Hubs & W. Brgs	✓
Rubber Mountings	✓	Brake Pads (F/R)	70% / 70%	Brake Discs (F/R)	80% / 80%
Comments: RPS BRAKE LIGHT NOT WORKING! REAR DIFF MOUNTINGS CRACKED				Modifications	(Y) / N
				Mech Grade (%)	70%

Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	NO
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L. Range	✓ / ✓	Diff Locks(s)	—	Steering Feedback	✓
Comments:					

Recommended Repairs and/or Final Comments

WA Final Assessment / %				WA Warranty
Practically As-new/	Excellent /	Good / 70%	Fair /	Needs Work /
				—