

Due Diligence					
Report Date	17/09/2026	Inspected By	RONAK	Supervisor	RONAK
Y.O.M	2019	Make & Model	MAZDA CX-5	Model Code	SIKACTIV
Reg. No. (if appl.)	—	VIN Number	KF5P-30A306	Engine No.	—
Mileage (Km)	35347km	Mileage Verified	✓	Use Country	JAPAN
Logbook Ver. (if appl.)	—	Previous Owners	—	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	X / ✓ ✓	Original Handbook	—	Spare Key	TBC
Service History Ver.	—	Last Service (Km)	—	Next Service (Km)	35347km

Body/Exterior Inspection	
	D = Dent S = Scratch M = Missing Trim RP = Repainted SR = Surface Rust R = Moderate Rust CR = Corrosion C = Crack / Chip
	General Comments: MINOR SCRATCHES
	Structural & Underbody Comments: NO RUST / CORROSION
	Exterior Grade (%) 80x
	Structural & Underbody Grade (%) 90x

Interior Inspection			
Upholstery	✓	Dash & Plastics	✓
Seats Fuct. (inc belts)	✓	Floor Mats	✓
		Smoked In	NO
		Interior Grade (%)	90x

Mechanical Inspection					
Exterior Lights	✓	Wipers	✓	Tyre Tread Depth	OLD & CRACKING
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	✓
Eng. Ancillary Cpts.	✓	Eng. Blowby	NO	Eng. Oil Leaks	NO
Cooling System Test	✓	Heat Exchangers	✓	Other leaks	NO
Fuses & relays	✓	Fluids	✓	Exhaust System	✓
Shocks & Springs	✓	Sus. Bushings	✓	Boots & Shafts	✓
Ball Joints / Tie Rods	✓	Column & Rack	✓	Hubs & W. Brgs	✓
Rubber Mountings	✓	Brake Pads (F/R)	60x / 60x	Brake Discs (F/R)	80x / 80x
Comments:				Modifications	Y / N
				Mech Grade (%)	90x

Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	NO
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L. Range	— / —	Diff Locks(s)	—	Steering Feedback	✓
Comments:					

Recommended Repairs and/or Final Comments	
TIRES - OLD & CRACKING - REPLACE	

WA Final Assessment / %				WA Warranty
Practically As-new/	Excellent / 90x	Good. /	Fair /	Needs Work /
				TBC