


Due Diligence					
Report Date	07/10/2026	Inspected By	RONAK	Supervisor	RONAK
Y.O.M	2019	Make & Model	SUZUKI JIMNY	Model Code	SIERA
Reg. No. (if appl.)	—	VIN Number	JB74W-111718	Engine No.	K15B-1044959
Mileage (Km)	15,573km	Mileage Verified	✓	Use Country	JAPAN
Logbook Ver. (If appl.)	—	Previous Owners	—	Priv. / comm	PRIVATE
Spare Tyre, Jack, Tools	✓✓✓	Original Handbook	—	Spare Key	TBC
Service History Ver.	—	Last Service (Km)	—	Next Service (Km)	15,573km

Body/Exterior Inspection		
	D = Dent	General Comments: MINOR SCRATCHES NO DENT
	S = Scratch	
	M = Missing Trim	
	RP = Repainted	Structural & Underbody Comments: NO RUST / CORROSION
	SR = Surface Rust	
	R = Moderate Rust	
	CR = Corrosion	
	C = Crack / Chip	
Exterior Grade (%)		80%
Structural & Underbody Grade (%)		85%

Interior Inspection					
Upholstery	✓	Dash & Plastics	✓	Smoked In	NO
Seats Fuct. (inc belts)	✓	Floor Mats	✓	Interior Grade (%)	85%

Mechanical Inspection					
Exterior Lights	COMMENT	Wipers	COMMENT	Tyre Tread Depth	60% / OLD
Elec. Interior Equip.	✓	Infotainment	✓	HVAC System	✓
Eng. Ancillary Cpnets.	✓	Eng. Blowby	NO	Eng. Oil Leaks	NO
Cooling System Test	✓	Heat Exchangers	✓	Other leaks	NO
Fuses & relays	✓	Fluids	✓	Exhaust System	✓
Shocks & Springs	✓	Sus. Bushings	COMMENT	Boots & Shafts	✓
Ball Joints / Tie Rods	✓	Column & Rack	✓	Hubs & W. Brgs	✓
Rubber Mountings	✓	Brake Pads (F/R)	70% / —	Brake Discs (F/R)	80% / —
Comments:				Modifications	Y / (N)
				Mech Grade (%)	80%

Road Test Report					
Engine Start Up	✓	Braking	✓	NVH	NO
Engine Perf. & Acc.	✓	Gear Shifting	✓	Warning Lights	NO
4WD / L. Range	✓ / ✓	Diff Locks(s)	—	Steering Feedback	✓

Comments:

Recommended Repairs and/or Final Comments
RHS INDICATOR NOT WORKING RHS REAR PARKING LIGHT NOT WORKING RHS WATER LOOSE + WATER NOT GOING TO THE REAR REAR PARKING LIGHT BSENT

WA Final Assessment / %					WA Warranty
Practically As-new/	Excellent /	Good. / 80%	Fair /	Needs Work /	TBC