

# Preserving Your Community's Heritage

Specialized Tuckpointing & Masonry Restoration for Religious Facilities



From weathered stone bell towers to deteriorating century-old mortar joints, religious buildings face unique preservation challenges. For three decades, our skilled craftsmen have restored elaborate steeples, rehabilitated historic masonry facades, and stabilized aging foundations—all while working respectfully around worship schedules. We bring sacred spaces back to life, ensuring they continue serving congregations for generations to come.



## Common Problems

### What to Look For

#### Mortar Joint Problems

- Visible gaps between bricks or stone
- Mortar that crumbles when touched
- White mineral deposits on brick surfaces

#### Steeple & Bell Tower Concerns

- Stains or streaks on exterior walls
- Loose or missing architectural elements
- Interior water stains below tower areas

#### Windows & Door Issues

- Open or damaged caulking joints
- Rusting steel lintels
- Damaged masonry sills

#### Foundation & Structural Concerns

- Horizontal or stair stepping cracks in the walls
- Displaced or bulging masonry
- Vertical cracking - especially at corners

## Services

# How We Can Help



### Investigation & Budgeting

- Building condition assessments for religious structures
- Preservation planning for historic houses of worship
- Phased project budgeting to accommodate fundraising cycles



### Historic Preservation

- Restoration of decorative religious elements
- Period-appropriate materials matching
- Compliance with historical designation requirements



### Building Maintenance

- Preventative maintenance programs for religious buildings
- Seasonal inspections of vulnerable areas
- Moisture control systems for bell towers and basements



### Masonry & Concrete Restoration

- Bell tower and steeple repair
- Tuckpointing and mortar joint restoration
- Stone/brick facade preservation
- Foundation stabilization



### Masonry Staining

- Color matching for historical accuracy
- Aesthetic enhancement of restored elements
- Protective coatings for long-term preservation

## Case Study

# St. Michael Catholic Church

St. Michael Catholic Church faced a critical emergency when their historic bell tower collapsed, threatening the entire building's safety and deeply affecting the parish community.

TNT Tuckpointing executed a comprehensive restoration, repairing damaged masonry, reconstructing the bell tower, and restoring the structure's original beauty. Our expert craftsmanship preserved the church's historical integrity while ensuring it would safely serve its congregation for generations to come.



Before



After



# Connect With A Restoration Specialist



563-785-0120



josh@tnttuckpointing.com



www.tnttuckpointing.com

