

Total projection: 4-May-2028 / Hrs 4354:10 / Ldg 2,651 / APUH / APUS

**Company**

Owner: JetBee Czech s.r.o.  
Operator:

**Major Assemblies**

<b>Airframe</b>	Hawker 4000	<b>RC-57</b>	28-Apr-2026	3634:10 Hrs	1,931 Ldg	Hrs(APU)		
<b>Eng 1</b>	PW308A	<b>PCE-CE0139</b>	28-Apr-2026	3336:58 Hrs	1,988 Enc	2,121.16 ATC1	2,047.64 ATC3	
<b>Eng 2</b>	PW308A	<b>PCE-CE0140</b>	28-Apr-2026	3336:58 Hrs	1,988 Enc	2,121.16 ATC1	2,047.64 ATC3	
<b>APU 1</b>	GTCP36-150[HH]	<b>P-163</b>	15-Apr-2026	Hrs	APUS			

**Additional Information**

Program Type: Standard, Earliest due: 0 DAYS, 99 HRS, 1,269 LDG, 95 APUHRS

Cost:  
Man Hrs: 1.5+

**Analyst:** Derick Naude [dnaude2@jetsupport.com](mailto:dnaude2@jetsupport.com)

Task No	Description				CW	REQ	TOL	Categories	Time
SEQ	PN/SN							DUE	Remaining
<b>3400000</b>	<b>Navigation Database Updates</b>								
	34 A/F							RE (Due)	
	Expiration Date 14-May-2026			Mos	28-Apr-2026			14-May-2026	0 Days
	Brand C:340010			Hrs	3634:10				
				Ldg	1,931				
<b>240008</b>	<b>Electrical Power - Power Distribution Assemblies No 3 and No 4 (PDA) Fan Screen - Visually Inspect for Condition, Damage and Security Clean If Necessary</b>							RE	5-20, AWL
	24 A/F			Mos	28-Apr-2026	2	-/+7d	28-Jun-2026	45 Days (+7)
	Ref.:ALM04-00-00, Ref.:AMM24-30-01			Hrs	3634:10				
				Ldg	1,931				
<b>34-Company-EGPWS</b>	<b>EGPWS Database Update</b>							RE	
	34 A/F			Days	28-Apr-2026	56	+10d	30-Jun-2026	47 Days (+10)
				Hrs	3634:10				
				Ldg	1,931				
<b>ARC 2 ND EXT</b>	<b>Perform 2 nd Extension of Airworthiness Review Certificate.</b>							RE	
	5 A/F			Yrs		3	-30d	[08-Jul-2026]	55 Days
				Hrs					
				Ldg					
<b>850004</b>	<b>Renew Insurance Certificate</b>							RE	
	100 A/F			Mos	12-Jul-2025	12		12-Jul-2026	59 Days
	Expiration Date 12-Jul-2026			Hrs					
				Ldg					
<b>490014</b>	<b>APU Engine Fuel Filter Element - Remove and Replace Fuel Filter Element</b>							RE	5-20 <b>≈20-Jul-2026</b>
	49 APU1			Mos	25-Mar-2020				
	Ref.:AMM49-30-16			Hrs	995	1,000	-/+20	1995	95:20 Hrs (+20)
				APUS					
<b>290012</b>	<b>Hydraulic Power - Hydraulic Filter Module Inspection - Area Visual Inspection Area and Filter Differential Pressure Indicators Check</b>							RE	5-20 <b>≈07-Aug-2026</b>
	29 A/F			Mos	23-Jan-2026				
	Ref.:AMM29-10-09			Hrs	3633:30	100	-/+3%	3733:30	99:20 Hrs (+3)
				Ldg	1,930				
<b>520089</b>	<b>Doors - Left Main Landing Gear Inboard Door Bumper Guard Cap - Perform Main Landing Gear Inboard Door Bumper Guard Cap Inspection Procedure</b>							RE	5-20, AWL <b>≈07-Aug-2026</b>
	52 A/F			Mos	23-Jan-2026				
	Ref.:ALM04-00-00, Ref.:AMM52-80-00			Hrs	3633:30	100	-/+3%	3733:30	99:20 Hrs (+3)
				Ldg	1,930				
<b>520089</b>	<b>Doors - Right Main Landing Gear Inboard Door Bumper Guard Cap - Perform Main Landing Gear Inboard Door Bumper Guard Cap Inspection Procedure</b>							RE	5-20, AWL <b>≈07-Aug-2026</b>
	52 A/F			Mos	23-Jan-2026				
	Ref.:ALM04-00-00, Ref.:AMM52-80-00			Hrs	3633:30	100	-/+3%	3733:30	99:20 Hrs (+3)
				Ldg	1,930				

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN					DUE	Remaining
<b>250003</b>	<b>Equipment/Furnishing - Life Vest - Replacement.</b>				RE (Due)	
25 A/F		Mos	23-Jan-2026		[21-Sep-2026]	4.3 Months
	Expiration Date 12-Dec-2027	Hrs	3633:30			
	CALM Task:259006, Ref.:ALM04-00-00, Ref.:SDS 25-60-00	Ldg	1,930			
<b>240010</b>	<b>Electrical Power - Generator - Perform the Generator Oil Level Check Procedure</b>				RE	5-20 ≈13-Oct-2026
24 A/F	Left	Mos	29-May-2024			
	768362B	Hrs	3498:50	300	-/+3%	3798:50 164:40 Hrs (+9)
	0217	Ldg	1,848			
	Ref.:AMM12-10-55					
<b>240010</b>	<b>Electrical Power - Generator - Perform the Generator Oil Level Check Procedure</b>				RE	5-20 ≈13-Oct-2026
24 A/F	Right	Mos	29-May-2024			
	768362B	Hrs	3498:50	300	-/+3%	3798:50 164:40 Hrs (+9)
	0218	Ldg	1,848			
	Ref.:AMM12-10-55					
<b>520091</b>	<b>Doors - External Door Handle - Perform External Door Handle Stowed Stop Adjustment Procedure and Verify Handle Position is In Tolerance</b>				RE	5-20 ≈17-Nov-2026
52 A/F		Mos	23-Jan-2026			
		Hrs	3633:30	200	-/+3%	3833:30 199:20 Hrs (+6)
	Ref.:AMM52-10-03	Ldg	1,930			
<b>780013</b>	<b>Left Exhaust - Inspection of the Inside Surface of Nozzle for Damage to Finish</b>				RE	5-20 ≈17-Nov-2026
78 A/F		Mos	23-Jan-2026			
		Hrs	3633:30	200	-/+3%	3833:30 199:20 Hrs (+6)
	Ref:SRM 78-30-00	Ldg	1,930			
<b>780013</b>	<b>Right Exhaust - Inspection of the Inside Surface of Nozzle for Damage to Finish</b>				RE	5-20 ≈17-Nov-2026
78 A/F		Mos	23-Jan-2026			
		Hrs	3633:30	200	-/+3%	3833:30 199:20 Hrs (+6)
	Ref:SRM 78-30-00	Ldg	1,930			
<b>250008</b>	<b>Equipment/Furnishings - Flight Data Recorder Underwater Locator Beacon - Clean and Test</b>				RE	5-20, AWL
25 A/F		Mos	29-May-2024	24	-/+30d [12-Dec-2026]	7.1 Months (+30 Days)
	18717-00	Hrs	3498:50			
	BL105749	Ldg	1,848			
	Ref.:AMM25-60-10, Ref.:ALM04-00-00					
<b>23-Custom-CVR</b>	<b>Cockpit Voice Recorder (CVR) - Perform inspection of CVR recordings. (AMC 1 CAT.GEN.MPA195(b))</b>				RE	
23 A/F		Yrs	17-Dec-2024	2		17-Dec-2026 7.2 Months
	2100-1020-51	Hrs	3633:30			
	000715897	Ldg	1,930			
<b>31-Custom-FDR</b>	<b>Flight Data Recorder (FDR) - Perform inspection of FDR recordings. (AMC 1 CAT.GEN.MPA195(b))</b>				RE	
31 A/F		Yrs	17-Dec-2024	2		17-Dec-2026 7.2 Months
	2100-2043-01	Hrs	3633:30			
	000672116	Ldg	1,930			
<b>350001</b>	<b>Oxygen - Oxygen Bottle (Left Upper Aircraft) - Hydrostatic Test</b>				RE	5-10, AWL
35 A/F	No.3	Mos	23-Jan-2026	60		19-Jan-2027 8.3 Months
	4441043-022	Hrs	3633:30			
	00079-3228	Ldg	1,930			
	Hydrostatic Tested Date 19-Jan-2022					
	Ref.:ALM04-00-00, Ref.:AMM35-00-14					
<b>120014</b>	<b>Servicing - Lubricate Zone 540 Trailing Edge Lubrication Points as Specified</b>				RE	5-20
12 A/F		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
		Hrs	3633:30	600	-/+20	4233:30 599:20 Hrs (+20)
	Ref.:AMM12-20-02	Ldg	1,930			

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN					DUE	Remaining
<b>240001</b>	<b>Electrical Power - Main Battery, Check</b>				RE	5-10
24 A/F	No.1					
RG-380E/44K		Mos	23-Jan-2026	12	-/+1m	[23-Jan-2027] 8.5 Months (+31 Days)
70060489		Hrs	3633:30			
Ref.:Concorde Instructions 5-0171 in Chapter 24 CMM, Ref.:24-30-28AMM		Ldg	1,930			
<b>240001</b>	<b>Electrical Power - Main Battery, Check</b>				RE	5-10
24 A/F	No.2					
RG-380E/44K		Mos	23-Jan-2026	12	-/+1m	23-Jan-2027 8.5 Months (+31 Days)
70023503		Hrs	3633:30			
Ref.:24-30-28AMM, Ref.:Concorde Instructions 5-0171 in Chapter 24 CMM		Ldg	1,930			
<b>250005</b>	<b>Equipment/Furnishings - First Aid Kit (If Installed) - Check Kit, Make Sure it is Onboard and Complete</b>				RE	5-20
25 A/F	05-20-01					
422162		Yrs	23-Jan-2026	1		23-Jan-2027 8.4 Months
		Hrs	3633:30	600	-/+20	4233:30 599:20 Hrs (+20)
Ref:IPC25-60-01, Ref:AMM25-60-15		Ldg	1,930			
<b>330003</b>	<b>Lights - Emergency Lighting Battery Pack - Perform Capacity Test</b>				RE	5-20
33 A/F	Fwd					
RG-128-3		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
70022631		Hrs	3633:30	1,000	-/+20	4633:30 999:20 Hrs (+20)
Ref.:AMM33-50-35, Ref.:CMM24-00-00 (UPDATE NOTE: Cap test 91,6 %)		Ldg	1,930			
<b>330003</b>	<b>Lights - Emergency Lighting Battery Pack - Perform Capacity Test</b>				RE	5-20
33 A/F	Mid					
RG-128-3		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
70022630		Hrs	3633:30	1,000	-/+20	4633:30 999:20 Hrs (+20)
Ref.:AMM33-50-35, Ref.:CMM24-00-00 (UPDATE NOTE: Cap test 98,3 %)		Ldg	1,930			
<b>CE-19-04 / 1746XX-SIL-001</b>	<b>Full Face Oxygen Mask Inspection and Cleaning</b>				RE	
35 A/F						
		Yrs	23-Jan-2026	1		23-Jan-2027 8.4 Months
		Hrs	3633:30	750		4383:30 749:20 Hrs
		Ldg	1,930			
<b>490004</b>	<b>APU Support Structure - Inspect APU Engine Mounts, Mount Adapters, Exhaust Clamp and Isolators for Looseness and Damage Inspect APU Engine Struts for Looseness and Damage</b>				RE	5-20
49 A/F						
		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
Ref:AMM49-10-01, Ref:AMM49-10-03, Ref:AMM49-10-07, Ref:AMM49-20-09		Hrs	3633:30			
		Ldg	1,930			
		Hrs (APU)	1899:40	750	-/+20	2649:40 750 Hrs(APU) (+20)
<b>490005</b>	<b>APU Bleed Air System - Check for Air Leaks at Clamped Joints and Pipes</b>				RE	5-20
49 APU1						
		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
Ref:AMM49-20-02		Hrs	1899:40	750	-/+20	2649:40 750 Hrs (+20)
		APUS				
<b>490006</b>	<b>APU Load Control Valve - Check for for Cracks, Dents, or Deformation, or Other Damage that may affect Performance of the Valve</b>				RE	5-20
49 APU1						
109804-7		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
2199		Hrs	1899:40	750	-/+20	2649:40 750 Hrs (+20)
Ref:AMM49-50-01		APUS				
<b>490007</b>	<b>APU Surge Control Valve - Check for Cracks, Dents, or Deformation, or Other Damage that may affect Performance of the Valve</b>				RE	5-20
49 APU1						
3884538-6		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
NSN		Hrs	1899:40	750	-/+20	2649:40 750 Hrs (+20)
Ref:AMM49-50-04		APUS				

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN					DUE	Remaining
<b>490008</b>	<b>Air Inlet Door and Structure - Check Engine Air Inlet Door for Proper Operation and Check Condition of the Air Inlet Door and the Surrounding Airframe Structure</b>				RE	5-20
49 A/F		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
Ref:AMM49-50-02		Hrs	1399			
		Ldg	1,930			
		Hrs (APU)	1899:40	750	-/+20	2649:40 750 Hrs(APU) (+20)
<b>490009</b>	<b>APU Inlet Duct Boot Assembly - Check the Condition and Security of Duct Boot</b>				RE	5-20
49 A/F		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
Ref:AMM49-20-06		Hrs	3633:30			
		Ldg	1,930			
		Hrs (APU)	1899:40	750	-/+20	2649:40 750 Hrs(APU) (+20)
<b>490010</b>	<b>APU Exhaust - Check Exterior of the Airplane and APU Exhaust Duct In the Airplane Tailcone for Proper Exhaust Discharge and Structural Integrity</b>				RE	5-20
49 A/F		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
Ref:AMM49-80-01		Hrs	3633:30			
		Ldg	1,930			
		Hrs (APU)	1899:40	750	-/+20	2649:40 750 Hrs(APU) (+20)
<b>490011</b>	<b>Magnetic Drain Plug - Perform Inspection of Magnetic Drain Plug In Conjunction with APU Engine Oil System Drainage Procedure Change APU Engine Oil Filter Element</b>				RE	5-20
49 APU1		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
Ref:AMM12-10-07, Ref:AMM49-90-03, Ref:AMM49-90-07, Ref:AMM49-90-08		Hrs	1899:40	750	-/+20	2649:40 750 Hrs (+20)
		APUS				
<b>490012</b>	<b>APU Installation - Check APU Compartment for Fuel and Oil Leakage Check for Obstructions In the Air Inlet, Engine Exhaust, and Drains Visually Inspect Exhaust for Cracks or Deformation Visually Check for Loose or Frayed Wires Check for Corrosion</b>				RE	5-20
49 A/F		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
Ref:AMM49-20-00		Hrs	1399			
		Ldg	1,930			
		Hrs (APU)	1899:40	750	-/+20	2649:40 750 Hrs(APU) (+20)
<b>490013</b>	<b>APU Fuel Feed Line - Visual Inspection for Leaks, Cracks, Security and Evidence of Damage</b>				RE	5-20
49 A/F		Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
Ref:AMM49-20-01		Hrs	3633:30			
		Ldg	1,930			
		Hrs (APU)	1899	750	-/+20	2649 749:20 Hrs(APU) (+20)
<b>490025</b>	<b>Lubricating Oil System - Drain and Refill</b>				RE	
49 APU1		Mos	23-Jan-2026	12		23-Jan-2027 8.4 Months
		Hrs	3633:30	750		4383:30 2483:50 Hrs
		APUS	1,930			
<b>560002</b>	<b>Windows - Perform Left Front Windshield Surface Seal Inspection Procedure</b>				RE	5-20, AWL
56 A/F	Pilot	Mos	23-Jan-2026	12	-/+30d	23-Jan-2027 8.4 Months (+30 Days)
401-384000-0011		Hrs	3633:30	600	-/+20	4233:30 599:20 Hrs (+20)
10116H4535		Ldg	1,930			
Ref:AMM30-40-00, Ref:ALM04-00-00						

Task No	Description			CW	REQ	TOL	Categories	Time
SEQ	PN/SN						DUE	Remaining
<b>560002</b>	<b>Windows - Perform Right Front Windshield Surface Seal Inspection Procedure</b>						RE	5-20, AWL
56 A/F	Copilot							
401-384000-0012			Mos	23-Jan-2026	12	-/+30d	23-Jan-2027	8.4 Months (+30 Days)
12069H0870			Hrs	3633:30	600	-/+20	4233:30	599:20 Hrs (+20)
Ref.:ALM04-00-00, Ref.:AMM30-40-00			Ldg	1,930				
<b>79-PW308A-001</b>	<b>Oil System - Oil Change</b>						RE	EMM - Requirement
79 ENG1								
			Mos	23-Jan-2026	12		23-Jan-2027	8.4 Months
Ref:72-00-00-svc			Hrs	3336	600	-/+50	3936	599:02 Hrs (+50)
			Enc					
<b>79-PW308A-001</b>	<b>Oil System - Oil Change</b>						RE	EMM - Requirement
79 ENG2								
			Mos	23-Jan-2026	12		23-Jan-2027	8.4 Months
Ref:72-00-00-svc			Hrs	3336:18	600	-/+50	3936:18	599:20 Hrs (+50)
			Enc					
<b>120013</b>	<b>Servicing - Pneumatic (Air) Starter Oil - Perform Starter Oil Level Check Procedure</b>						RE	5-20 ≈25-Feb-2027
12 A/F	Left							
821600-7			Mos	23-Jan-2026				
201101013			Hrs	3633:30	300	-/+3%	3933:30	299:20 Hrs (+9)
Ref.:AMM12-10-50			Ldg	1,930				
<b>120013</b>	<b>Servicing - Pneumatic (Air) Starter Oil - Perform Starter Oil Level Check Procedure</b>						RE	5-20 ≈25-Feb-2027
12 A/F	Right							
821600-7			Mos	23-Jan-2026				
201101010			Hrs	3633:30	300	-/+3%	3933:30	299:20 Hrs (+9)
Ref.:AMM12-10-50			Ldg	1,930				
<b>Pkg Minor</b>	<b>Engine Minor Periodic Inspection</b>						RE	EMM - Requirement ≈28-Feb-2027
5 ENG1								
			Mos	14-Feb-2024				
			Hrs	3039:33	600	+30	3639:33	302:35 Hrs (+30)
			Enc	1,839				
<b>Pkg Minor</b>	<b>Engine Minor Periodic Inspection</b>						RE	EMM - Requirement ≈28-Feb-2027
5 ENG2								
			Mos	14-Feb-2024				
			Hrs	3039:33	600	+30	3639:33	302:35 Hrs (+30)
			Enc	1,839				
<b>720020</b>	<b>Download ECC for FADEC Faults</b>						RE	EMM - Requirement ≈28-Feb-2027
72 ENG1								
			Mos	14-Feb-2024				
			Hrs	3039:33	600		3639:33	302:35 Hrs
			Enc	1,839				
<b>720020</b>	<b>Download ECC for FADEC Faults</b>						RE	EMM - Requirement ≈28-Feb-2027
72 ENG2								
			Mos	14-Feb-2024				
			Hrs	3039:33	600		3639:33	302:35 Hrs
			Enc	1,839				
<b>FR-H4-105433 Rev. B</b>	<b>4 Year Inspection of the Left and Right Hand Engine Exhaust Nozzles per the Field Repair Procedure FR-H4-105433 Rev. B</b>						RE	
78 A/F								
			Yrs	31-Mar-2023	4		31-Mar-2027	10.7 Months
			Hrs	2760:45				
			Ldg	1,469				
<b>250007</b>	<b>Equipment/Furnishings - Emergency Locator Transmitter - Operational Check</b>						RE	5-20
25 A/F								
453-5000								
170-12041			Mos	15-Apr-2026	12	-/+30d	15-Apr-2027	11.2 Months (+30 Days)
Ref.:AMM25-60-01			Hrs	3634:10				
			Ldg	1,931				

Task No	Description		CW	REQ	TOL	Categories	Time
SEQ	PN/SN					DUE	Remaining
<b>350001</b>	<b>Oxygen - Portable Oxygen Cabin - Hydrostatic Test</b>			RE		5-10, AWL	
35 A/F		Mos	28-Apr-2026	60		[19-May-2027]	1 Year
176961-15		Hrs	3634:10				
613965601		Ldg	1,931				
Hydrostatic Tested Date 19-May-2022							
CALM Task:359001, Ref.:ALM04-00-00, Ref.:AMM35-00-14							
<b>ARC FULL REVIEW</b>	<b>Perform Airworthiness Review Inspection and Recommendation (ARC).</b>			RE			
5 A/F		Yrs	08-Jul-2024	3	-3m	08-Jul-2027	1.2 Years
		Hrs					
		Ldg					
<b>250010</b>	<b>Equipment/Furnishings - Emergency Locator Transmitter Battery Pack - Replacement</b>			RE		5-20, AWL, Replacement	
25 A/F		Mos	02-Dec-2022	60		[31-Jul-2027]	1.2 Years
452-0133		Hrs	2647:10				
395709-040		Ldg	1,413				
Manufactured Date 31-Jul-2022							
Ref.:ALM04-00-00, Ref.:AMM25-60-01							
<b>350001</b>	<b>Oxygen - Oxygen Bottle (Right Lower Aircraft) - Service Life</b>			RE		5-10, AWL, Life Limit	
35 A/F	No.2	Yrs	23-Jan-2026	15		31-Aug-2027	1.3 Years
4441716-050		Hrs	3633:30				
LX00320404		Ldg	1,930				
Manufactured Date 31-Aug-2012							
Ref.:ALM04-00-00, Ref.:AMM35-00-14							
<b>270008</b>	<b>Flight Controls - Rudder Power Control Unit (PCU), Replacement</b>			RE		5-10, AWL, Replacement	<b>≈08-Sep-2027</b>
27 A/F	No.1	Mos					
920590-105		Hrs		4,125		4125	490:50 Hrs
0086		Ldg					
Ref.:ALM04-00-00, Ref.:AMM27-20-03							
<b>270008</b>	<b>Flight Controls - Rudder Power Control Unit (PCU), Replacement</b>			RE		5-10, AWL, Replacement	<b>≈08-Sep-2027</b>
27 A/F	No.2	Mos					
920590-105		Hrs		4,125		4125	490:50 Hrs
0168		Ldg					
Ref.:ALM04-00-00, Ref.:AMM27-20-03							
<b>05-20-03</b>	<b>1,800 Hour Inspections</b>			RE		5-20	<b>≈20-Nov-2027</b>
5 A/F		Mos	10-Jun-2022				
		Hrs	2383	1,800	-/+20	4196:55	562:45 Hrs (+20)
		Ldg	1,233				
<b>210002</b>	<b>Integrated Cabin Pressure Control System (CPCS) Valve P/N 2119050-3 - Replace spring P/N 4245262-1 every 4,200 hours.</b>			RE		5-10, AWL, Replacement	<b>≈23-Nov-2027</b>
21 A/F		Mos					
		Hrs		4,200		4200	565:50 Hrs
		Ldg					
ALM:04-00-00, AMM:21-30-01							
<b>250008</b>	<b>Equipment/Furnishings - Cockpit Voice Recorder Underwater Locator Beacon - Clean and Test</b>			RE		5-20, AWL	
25 A/F		Mos	23-Jan-2026	24	-/+30d	[02-Dec-2027]	1.6 Years (+30 Days)
DK120		Hrs	3633:30				
BL106568		Ldg	1,930				
Ref.:ALM04-00-00, Ref.:AMM25-60-10							
<b>05-00-601</b>	<b>600 Hr/24 Mos Inspection Clock - Review Chapter 05-00-00 "Table 602. Inspection Intervals" for Next Inspection Due</b>			RE		5-00	<b>≈28-Dec-2027</b>
5 A/F	05-20-01	Mos	23-Jan-2026	24	-/+30d	23-Jan-2028	1.7 Years (+30 Days)
		Hrs	3633:30	600	-/+20	4233:30	599:20 Hrs (+20)
		Ldg	1,930				
<b>05-20-01</b>	<b>600 Hour Inspections</b>			RE		5-20	<b>≈28-Dec-2027</b>
5 A/F		Mos	23-Jan-2026				
		Hrs	3633:30	600	-/+20	4233:30	599:20 Hrs (+20)
		Ldg	1,930				

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN					DUE	Remaining
<b>250004</b>	<b>Equipment/Furnishings - Life Vests (P/N AC-2000) - Visually Inspect for Condition and Integrity of Vacuum Pack Replace if Vacuum Lost or Item Damaged</b>				5-20, AWL	≈28-Dec-2027
25 A/F	05-20-01	Mos	23-Jan-2026			
		Hrs	3633:30	600	-/+20	4233:30 599:20 Hrs (+20)
		Ldg	1,930			
	CALM Task:259007, Ref:ALM04-00-00, Ref:SDS25-60-00					
<b>320038</b>	<b>Landing Gear - Perform Normal Landing Gear Operational Check Procedure</b>				5-20, AWL, CMR	≈28-Dec-2027
32 A/F	05-20-01	Mos	23-Jan-2026			
		Hrs	3633:30	600		4233:30 599:20 Hrs
		Ldg	1,930			
	Ref:ALM04-00-00, Ref:AMM32-00-00					
<b>350003</b>	<b>Oxygen - Protective Breathing Equipment - Perform Protective Breathing Equipment Inspection Procedure</b>				5-20, AWL	≈28-Dec-2027
35 A/F	05-20-01	Mos	23-Jan-2026			
		Hrs	3633:30	600	-/+20	4233:30 599:20 Hrs (+20)
		Ldg	1,930			
	Ref:ALM04-00-00, Ref:AMM35-30-02					
<b>520005</b>	<b>Doors - Perform Cabin Door Functional Check Procedure</b>				5-20, AWL	≈28-Dec-2027
52 A/F	05-20-01	Mos	23-Jan-2026			
		Hrs	3633:30	600	-/+20	4233:30 599:20 Hrs (+20)
		Ldg	1,930			
	Ref:ALM04-00-00, Ref:AMM52-10-01					
<b>520092</b>	<b>Doors - Cabin Door Actuator Assembly - Visually Inspect for Condition, Cracks, Damage, Corrosion, Loose or Missing Fasteners and Security</b>				5-20, AWL	≈28-Dec-2027
52 A/F	05-20-01	Mos	23-Jan-2026			
		Hrs	3633:30	600	-/+20	4233:30 599:20 Hrs (+20)
		Ldg	1,930			
	Ref:ALM04-00-00, Ref:AMM52-10-36					
<b>720001</b>	<b>Engines - Inspect Engine in Accordance with Chapter 5 of the PWC Maintenance Manual</b>				5-20	≈28-Dec-2027
72 ENG1	05-20-01	Mos	23-Jan-2026			
		Hrs	3336:18	600	-/+20	3936:18 599:20 Hrs (+20)
		Enc				
<b>26324 Rev 2</b>	<b>Replacement of Drain Valve Assembly</b>				Category 3	≈28-Dec-2027
73 ENG1		Mos				
		Hrs		600		≈3936:18 599:20 Hrs
		Enc				
<b>490003</b>	<b>APU Engine Igniter Plug - Removal, Cleaning, Inspection and Installation</b>				5-20	≈04-Jan-2028
49 APU1		Mos	14-Feb-2024			
Unknown		Hrs	1768:50	750	-/+20	2518:50 619:10 Hrs (+20)
Unknown		APUS	1,750			
	Ref:AMM49-40-03					
<b>260013</b>	<b>Fire Protection - Cabin Portable Fire Extinguisher - Perform Weight Check</b>				5-20	
26 A/F	No.1	Mos	23-Jan-2026	24	-/+30d	23-Jan-2028 1.7 Years (+30 Days)
339TS		Hrs	3633:30			
I-83989266		Ldg	1,930			
12-Dec-2025						
	Ref:AMM26-20-20, Ref:AMM26-20-19					
<b>260013</b>	<b>Fire Protection - Cabin Portable Fire Extinguisher - Perform Weight Check</b>				5-20	
26 A/F	No.2	Mos	23-Jan-2026	24	-/+30d	23-Jan-2028 1.7 Years (+30 Days)
339TS		Hrs	3633:30			
I-83989267		Ldg	1,930			
12-Dec-2025						
	Ref:AMM26-20-19, Ref:AMM26-20-20					
<b>260013</b>	<b>Fire Protection - Cabin Portable Fire Extinguisher - Perform Weight Check</b>				5-20	
26 A/F	No.3	Mos	23-Jan-2026	24	-/+30d	23-Jan-2028 1.7 Years (+30 Days)
339TS		Hrs	3633:30			
I-83989265		Ldg	1,930			
26-Jan-2025						
	Ref:AMM26-20-19, Ref:AMM26-20-20					

Task No	Description		CW	REQ	TOL	Categories	Time
SEQ	PN/SN					DUE	Remaining
<b>260013</b>	<b>Fire Protection - Cockpit Portable Fire Extinguisher - Perform Weight Check</b>			RE		5-20	
26 A/F		Mos	23-Jan-2026	24	-/+30d	23-Jan-2028	1.7 Years (+30 Days)
339TS		Hrs	3633:30				
I-83989264		Ldg	1,930				
12-Dec-2025							
Ref:AMM26-20-19, Ref:AMM26-20-20							
<b>340002</b>	<b>Navigation - Standby Altimeter Module - Recertify</b>			RE		5-20	
34 A/F		Mos	23-Jan-2026	24	-/+30d	23-Jan-2028	1.7 Years (+30 Days)
27301-01-01		Hrs	3633:30				
M025823		Ldg	1,930				
Certified Date 23-Jan-2026							
Ref:AMM34-10-00							
<b>340003</b>	<b>Navigation - ATC Transponder - Recertify</b>			RE		5-20	
34 A/F	No.1	Mos	23-Jan-2026	24	-/+30d	23-Jan-2028	1.7 Years (+30 Days)
7517402-970		Hrs	3633:30				
1105H274		Ldg	1,930				
Certified Date 23-Jan-2026							
Ref:AMM34-50-31							
<b>340003</b>	<b>Navigation - ATC Transponder - Recertify</b>			RE		5-20	
34 A/F	No.2	Mos	23-Jan-2026	24	-/+30d	23-Jan-2028	1.7 Years (+30 Days)
7517402-970		Hrs	3633:30				
1012G820		Ldg	1,930				
Certified Date 23-Jan-2026							
Ref:AMM34-50-31							
<b>340004</b>	<b>Navigation - Air Data Computer Module - Recertify</b>			RE		5-20, AWL	
34 A/F	No.1	Mos	23-Jan-2026	24	-/+30d	23-Jan-2028	1.7 Years (+30 Days)
HG1153CA04		Hrs	3633:30				
10054241		Ldg	1,930				
Certified Date 23-Jan-2026							
Ref:ALM04-00-00, Ref:AMM34-10-01							
<b>340004</b>	<b>Navigation - Air Data Computer Module - Recertify</b>			RE		5-20, AWL	
34 A/F	No.2	Mos	23-Jan-2026	24	-/+30d	23-Jan-2028	1.7 Years (+30 Days)
HG1153CA04		Hrs	3633:30				
10054242		Ldg	1,930				
Certified Date 23-Jan-2026							
Ref:ALM04-00-00, Ref:AMM34-10-01							
<b>72-PW308A-004</b>	<b>Low Utilization Inspection (LUI) Program</b>			RE		EMM - Requirement	
72 ENG1		Mos	23-Jan-2026	24		23-Jan-2028	1.7 Years
		Hrs					
		Enc					
Ref:72-00-00-ic							
<b>72-PW308A-004</b>	<b>Low Utilization Inspection (LUI) Program</b>			RE		EMM - Requirement	
72 ENG2		Mos	23-Jan-2026	24		23-Jan-2028	1.7 Years
		Hrs					
		Enc					
Ref:72-00-00-ic							
<b>FR-H4-105433 Rev. B</b>	<b>2 Year Inspection of the Left and Right Hand Engine Exhaust Nozzles per the Field Repair Procedure FR-H4-105433 Rev. B</b>			RE			
78 A/F		Yrs	23-Jan-2026	2		23-Jan-2028	1.7 Years
		Hrs	3633:30				
		Ldg	1,930				