



ACSE4601/ARCN4200
BUILDING PATHOLOGY

SAINT BRIGID'S CENTRE FOR THE ARTS
310 St. Patrick St, Ottawa, ON K1N 5K4

GROUP 10:

ISHIKA SAXENA 101227026
FATIMA FARIS 101222415
TONILOBA KUMAPAYI 101236693
MARIIA PAPKHOMCHUK 101287201
AMY HALASZ 101263778
MAGGIE SHEARDOWN 101186104

NOTES:
NORTH ELEVATION OF THE BUILDING

LEGEND:

	BIOLOGICAL GROWTH
	CHEMICAL DETERIORATION - GYPSUM CRUST
	CHEMICAL DETERIORATION - OXIDIZATION
	SPALLED CONCRETE
	SURFACE DELAMINATION
	DISCOLOURATION DUE TO MOISTURE INGRESS
	MATERIAL LOSS
	WOOD DETERIORATION
	STONE WEATHERING AND DETERIORATION
	MORTAR JOINT CRACKING

ORTHO-CORRECTED IMAGE DRAFTED BY:
AMY HALASZ

DETERIORATION DRAWING BY:
ISHIKA SAXENA

SCALE: 1:200
DATE: 19/04/2026

0 200 400