

# RIVIX

# CASE STUDY



NEXGEN ENERGY LTD. • MINING AND ENERGY • CANADA • 22 DAYS • 7,500 UNITS



## OVERVIEW

NexGen Energy required protective uniforms for both surface and underground work.

## CHALLENGES

They needed several layers of fabric weights for different zones on the site. We had to source materials that performed consistently across changing conditions. Their order needed to arrive before winter operations started again.

## SOLUTION

We ran a few early samples and added removable layers so their staff could adjust based on the jobsite. We made sure every movement and protection stayed balanced across each layer. Their safety team checked the samples on site before production moved forward.

## RESULT

All 7,500 pieces were completed in 22 days on time before the winter work resumed. Their teams gave positive feedback for their new uniforms.