

Inspection, Maintenance & Repair Services

# Stronelairg Wind Farm

## Objectives

Inspect the met mast to ensure it is structurally sound and the ladder, fall arrest system safe for use.

## Our Solution

Aurora provided an experienced inspector and safety person to ensure the work was completed with zero harm.

Inspect the met mast to ensure it is structurally sound and the ladder, fall arrest system safe for use

## At a Glance

### Challenges


Weather conditions, heavy snow delayed access to the site which resulted in reduced exposure times.

### Value to client

A competent team carried out a safe inspection with good collaborative communications.



## Contact Us

 [info@auroraenergy.co](mailto:info@auroraenergy.co)

 [auroraenergy.co](http://auroraenergy.co)