





SERIES: 3000-TH THERMALLY BROKEN
ALUMINUM IMPACT CASEMENT WINDOWS

GLAZING: $1\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS




1



2

SERIES: 3000-TH THERMALLY BROKEN
ALUMINUM IMPACT CASEMENT WINDOWS


GLAZING: $1\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS



SOL-A-TROL

aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035


3




4

SERIES: 3000—TH THERMALLY BROKEN
ALUMINUM IMPACT CASEMENT WINDOWS

GLAZING: $1\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS



aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035




5

SERIES: 3000-TH THERMALLY BROKEN
ALUMINUM IMPACT CASEMENT WINDOWS


GLAZING: $1\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS



6




7



SERIES: 3000—TH THERMALLY BROKEN
ALUMINUM IMPACT CASEMENT WINDOWS

GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS



SOL—A—TROL

aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035