


GLAZING:
1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT
GLASS




SERIES: 5000—TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL



GLAZING:
1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT
GLASS


LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN

1



2


SERIES: 5000—TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL




GLAZING:
1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT
GLASS

LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN

3




SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL




GLAZING:
1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT
GLASS

LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN




SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL




GLAZING:
1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT
GLASS


LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN



SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL



GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS




SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL WITH SERIES 3000-TH
THERMALLY BROKEN CASEMENT WINDOW




GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

1



LAMINATED GLASS INTERIOR AND EXTERIOR
OPTION SHOWN

2




SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL WITH SERIES 3000-TH
THERMALLY BROKEN CASEMENT WINDOW




GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

3



LAMINATED GLASS INTERIOR AND EXTERIOR
OPTION SHOWN

4



SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL WITH SERIES 3000-TH
THERMALLY BROKEN CASEMENT WINDOW




SOL-A-TROL

aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035


GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

5



LAMINATED GLASS INTERIOR AND EXTERIOR
OPTION SHOWN

6



SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL WITH SERIES 3000-TH
THERMALLY BROKEN CASEMENT WINDOW




SOL-A-TROL

aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035


GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

7




LAMINATED GLASS INTERIOR AND EXTERIOR
OPTION SHOWN

8



SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL WITH SERIES 3000-TH
THERMALLY BROKEN CASEMENT WINDOW




SOL-A-TROL

aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035


GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

9




LAMINATED GLASS INTERIOR AND EXTERIOR
OPTION SHOWN

10




SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL WITH SERIES 3000-TH
THERMALLY BROKEN CASEMENT WINDOW




SOL-A-TROL

aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035

GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS




SERIES: 5000—TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL
WITH SERIES 3000—TH THERMALLY BROKEN
PROJECT—OUT WINDOW




GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

1




LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN

2



SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL
WITH SERIES 3000-TH THERMALLY BROKEN
PROJECT-OUT WINDOW




SOL-A-TROL

aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035


GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

3



LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN

4




SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL
WITH SERIES 3000-TH THERMALLY BROKEN
PROJECT-OUT WINDOW




GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

5




LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN

6




SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL
WITH SERIES 3000-TH THERMALLY BROKEN
PROJECT-OUT WINDOW




GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

7



LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN

8




SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL
WITH SERIES 3000-TH THERMALLY BROKEN
PROJECT-OUT WINDOW




GLAZING: 1 $\frac{5}{16}$ " LAMINATED
INSULATED IMPACT GLASS

9



LAMINATED GLASS AT INTERIOR AND EXTERIOR
OPTION SHOWN

10



SERIES: 5000-TH THERMALLY BROKEN
ALUMINUM IMPACT WINDOW WALL
WITH SERIES 3000-TH THERMALLY BROKEN
PROJECT-OUT WINDOW



SOL-A-TROL

aluminum products
4101 N.W. 132nd Street
Miami, Florida 33054
Phone: (305) 681-2020
Fax: (305) 681-2035