

CG Motorsports
11880 Hammersmith Way 150, Richmond, BC V7A 5C8
(604) 275-6638 | info@cgmotorsports.com




[Inspection Report](#) Visit Details

Your Visit

[View Details →](#)

Kurumasource Auto Sales LTD 2013 BMW M3
RO# 34726 | Time In 07/27/2026 04:22 PM
Service Advisor W Bowe

Vehicle Health



Technician Findings

! ENGINE OIL LEAKS

Finding:
Sweat from left side bank 2 valve cover monitor for now



! TRANSMISSION FLUID LEAKS

Finding:
Sweat from DCT oil pan monitor for now



Inspections Performed

Simple Multi-Point Vehicle Inspection	
Inspection Task	Findings
STANDARD INSPECTION	
✓ WIPER BLADES	
✓ TIRE PRESSURES	35/36
✓ FRONT TIRE TREAD DEPTH	6.5mm

Inspection Task	Findings
 REAR TIRE TREAD DEPTH	4.5
 FRONT BRAKE PAD MEASUREMENT	New - 12mm
 REAR BRAKE PAD MEASUREMENT	New - 12mm
 WARNING LIGHTS ON	
 EXTERIOR LIGHTS	
SUSPENSION	
 ROTATION NEEDED?	
 ALIGNMENT NEEDED?	
 WEAR PATTERN DAMAGE	
 BRAKE LINE	
 BUSHINGS	
 STRUTS	
DRIVELINE	
 DRIVELINE, DRIVESHAFT(S), AXLES	
UNDERHOOD	
 ENGINE AIR FILTER	
 EXHAUST SYSTEM COMPONENTS	
 HOSES & BELTS	
 WASHER FLUID	
 TRANSMISSION FLUID LEAKS	Sweat from DCT oil pan monitor for now 
 ENGINE OIL LEAKS	Sweat from left side bank 2 valve cover monitor for now  
 POWER STEERING LEAKS	
 COOLANT LEAKS	

Inspection Task	Findings
✓ DIFFERENTIAL LEAK	
✓ BRAKE FLUID	
MAINTENANCE	
✓ RECOMMENDED MILEAGE MAINTENANCE	
✓ OTHER RECOMMENDED SERVICES	
2 technician concerns found	

Vehicle Drop off/Check-in quick inspection



Inspection Task	Findings
DAMAGE INSPECTION	
✓ HOOD	
✓ FRONT BUMPER	
✓ DRIVER SIDE	
✓ REAR BUMPER	
✓ PASSENGER SIDE	
✓ INTERIOR	
✓ TRUNK	

Inspection Task	Findings
WHEELS	
HEADLIGHTS AND TAILLIGHTS	
WINDSHIELD	
0 technician concerns found	

Need a copy for your records?

Print

Questions? Contact Us.

Call

Email

Text

