

CG Motorsports

11880 Hammersmith Way 150, Richmond, BC V7A 5C8
(604) 275-6638 | info@cgmotorsports.com

[Inspection Report](#)[Visit Details](#)**Your Visit**[View Details →](#)

Kurumasource Auto Sales LTD 2013 BMW X1

RO# 35478 | Time In 10/09/2026 07:14 AM

Service Advisor J Campbell

Vehicle Health

Checked & Okay May Require Attention Soon Requires Immediate Attention

**Technician Findings****✖ ENGINE OIL LEAKS**

Finding:
oil filter housing starting to leak
oil pan and possibly rear main are leaking

**✖ OTHER RECOMMENDED SERVICES**

Finding:
brake fluid and front brake pad service due

**✖ BRAKE FLUID**

Finding:
brake fluid due

✖ FRONT BRAKE PAD MEASUREMENT

Finding:
4mm

⚠ TRANSMISSION FLUID LEAKS

Finding:
transmission pan possibly leaking or could be residue carried towards the rear by oil leak



 BUSHINGS



Finding:
both rear thrust arm bushings are cracking



 REAR BRAKE PAD MEASUREMENT



Finding:
5mm

Inspections Performed



Simple Multi-Point Vehicle Inspection



Inspection Task	Findings
STANDARD INSPECTION	
 WIPER BLADES	
 TIRE PRESSURES	
 FRONT TIRE TREAD DEPTH	6mm manufactured in 2021
 REAR TIRE TREAD DEPTH	6mm tires manufactured in 2021
 FRONT BRAKE PAD MEASUREMENT	4mm
 REAR BRAKE PAD MEASUREMENT	5mm
 WARNING LIGHTS ON	
 EXTERIOR LIGHTS	
SUSPENSION	
 ROTATION NEEDED?	
 ALIGNMENT NEEDED?	
 WEAR PATTERN DAMAGE	
 BRAKE LINE	

both rear thrust arm bushings are cracking

Inspection Task	Findings
 BUSHINGS	 
 STRUTS	
DRIVELINE	
 DRIVELINE, DRIVESHAFT(S), AXLES	
UNDERHOOD	
 ENGINE AIR FILTER	
 EXHAUST SYSTEM COMPONENTS	
 HOSES & BELTS	
 WASHER FLUID	
 TRANSMISSION FLUID LEAKS	transmission pan possibly leaking or could be residue carried towards the rear by oil leak 
 ENGINE OIL LEAKS	oil filter housing starting to leak oil pan and possibly rear main are leaking   
 POWER STEERING LEAKS	
 COOLANT	
 DIFFERENTIAL LEAK	
 BRAKE FLUID	brake fluid due
MAINTENANCE	
 RECOMMENDED MILEAGE MAINTENANCE	
 OTHER RECOMMENDED SERVICES	brake fluid and front brake pad service due  
7 technician concerns found	

Vehicle Drop off/Check-In Quick Inspection					
Inspection Task	Findings				
DAMAGE INSPECTION					
✓ WINDSHIELD					
✓ HOOD					
✓ FRONT BUMPER	  				
✓ DRIVER SIDE					
✓ REAR BUMPER	  				
✓ TRUNK					
✓ PASSENGER SIDE					
✓ HEADLIGHTS AND TAILLIGHTS	    				
✓ WHEELS					

Inspection Task	Findings
	
 INTERIOR	
 VIN STICKER / TIRE STICKER / REGISTRATION	
0 technician concerns found	

Need a copy for your records?

 Print

Questions? Contact Us.

 Call

 Email

 Text

