

TEST RESULTS SUMMARY

REPORT FOR: XYZ Sprinkler Company
2357 VENTURA DR
STE 108
SAINT PAUL MN 55125

PO: Example
Job: Corrosion and MIC Example Report

Job Number: 67105
Date Received: 06/15/2026
Report Date: 06/17/2026
Page: 1 of 1

Sample Number	Sample ID	Product	Sampling Point	Pass/Fail
1	Example	Water (Corrosion & MIC Analysis)	Water Supply	See Report