

SAMPLE TEST RESULTS

REPORT FOR: XYZ Sprinkler Company
2357 VENTURA DR
STE 108
SAINT PAUL MN 55125

PO: Example
Job ID: Diesel Example Report

Job Number: 67106
Date Received: 06/15/2026
Report Date: 06/17/2026
Page: 1 of 1

Sample Information	Test	Method (LBTR-)	Requirement	Test Value	Test Result
Sample Number: 1 Sample ID: Example System Volume: Example Product: Diesel Fuel Sampling Point: Bottom	<u>Physical Properties</u>				
	Water and Sediment, % by volume	3701	≤0.05% by volume	0.01	Pass
	<u>Performance Properties</u>				
	Oxidation Stability, hours	3702	≥6 hours	6.0	Pass
	<u>Composition</u>				
	Acid Number, mg KOH/g	3700	≤0.3 mg KOH/g	0.28	In Spec
	<u>Interpretations</u>				
	Overall Result		Pass	Pass	Pass

Comments:
This diesel fuel was tested as required by the 2026 edition of NFPA 25, section 8.3.4.1, and the 2025 edition of NFPA 110, section 8.3.7. It met or exceeded all requirements.


Alyssa Dunn, General Manager

It is the responsibility of the property owner or designated representative to ensure the sample information is correct and to correct deficiencies or impairments, including identifying and replacing any recalled products. The results relate only to the sample tested using a limited number of laboratory-scale methods and do not guarantee the system will operate properly. This report shall not be reproduced except in full without the written consent of Dyne Fire Protection Labs, LLC.
*Uncertainty values available upon request



FIRE PROTECTION LABS
dyne

2357 Ventura Dr Suite 108
Woodbury MN 55125
(800)632-2304
dyne.lab@nfpaglobal.com