

# SSW Group Ltd – Case Study



## Project Overview

SSW Group Ltd – Case Study SSW Group Ltd was contracted by Deep Group Ltd for a full recladding of two residential buildings located at 10 Marsh Wall, Canary Wharf, London. The project involved the removal and reinstatement of the façade across 7 floors, spanning a total of 4,800 m<sup>2</sup> over a one-year period from 2024 to 2025.

## Scope of Work

The works were divided into four distinct phases:

1. Removal of Existing Tiles and Rail System
2. Repatching of Structural Holes
3. Installation of High-Performance Rockwool Insulation
4. Installation of Fire Barriers (Siderise)
5. Reinstallation of Tiles with New Support Systems Materials Used- Rockwool insulation- Mastic sealants- External façade tiles- Screws, rails, and fixing systems

## Compliance & Reporting:

- Full Siderise Installation Report

Generated and submitted via Power Apps platform for full traceability and compliance documentation.

- Live Project Tracking

All site activities, snagging, and progress updates tracked in real time through FieldWire.

## Materials Used

- Rockwool insulation
- Mastic sealants
- External facade tiles
- Screws, rails, and fixing systems

## Challenges & Solutions

- Tight access at Canary Wharf required careful coordination with local authorities for safe logistics.
- Hidden wall damage revealed after tile removal was repaired using compliant patching systems.
- Bad weather was mitigated with flexible scheduling and protective site management.

## Client Feedback

Deep Group Ltd expressed high satisfaction with the quality, communication, and timely SSW Group Ltd – Case Study delivery of our work. The professionalism of the SSW team was highlighted during final handover inspections.

## Results

- 4,800 m<sup>2</sup> completed across 2 buildings
- Delivered within the agreed 2024–2025 timeline
- Full compliance with fire and insulation standards
- Zero health & safety incident

## Photo Document











